

NOT Authorized
 L1 Prng @ 2200hr
 Murray Abu Pain
 3 days

EM Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emautosolution@singnet.com.sg

Vehicle number: SLF9382P Vehicle Made & Model: MITSUBISHI OUTLANDER

Qty	List Items	Amount \$
1	Front bumper <i>863</i>	Bu 935.00 ✓
1	Front bumper CTR pad <i>321</i>	nd 486.00 ✓
1	Front bumper lower guard	sn 526.00 X
1	Front bumper chrome moulding - RH - Top	nd 132.00 ✓
1	Front bumper chrome moulding - RH - CTR	CM 295.00 ✓
1	Front bumper chrome moulding - RH - Lower	ln 262.00 X
1	Front bumper spray nozzle cover	mit 68.00 ✓
1	Front bumper fog lamp - RH	pr 385.00 X
1	Front bumper fog lamp cover	mit 136.00 ✓
1	Front bumper fog lamp moulding	sn 126.00 X
1	Front bumper side protector - RH	dis 192.00 ✓
2	Front bumper side retainers - L/R @ 65	dis 130.00 ✓
1	Front bumper reinforcement	R 655.00 X
1	Front fender - RH	R 735.00 X
1	Front fender protector	ln 392.00 X
1	Front fender inner shield	sn 189.00 X
1	Front headlamp - RH	ln 2,550.00 X
1	Front sport wheel - RH	sn 835.00 X
1	Front shock absorber - RH	sn 486.00 X
1	Front lower arm	sn 495.00 X
1	Front knuckle arm	sn 510.00 X
1	Front wheel hub bearing	sn 425.00 X
1	Wiper tank	sn 192.00 X
Sub-total		11,137.00
Less 10%		1,113.70
Total List		10,023.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) *Page 1 of 2* surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle number: SLF9382P

Vehicle Made & Model: MITSUBISHI OUTLANDER

Special Nett Items

1 set	Front bumper clip	<i>nn</i>	60.00	✓
1 set	Front fender inner shield clip	<i>nn</i>	60.00	X
1	Front tyre - RH	<i>pr</i>	280.00	X
Total Special Nett			<u>400.00</u>	

Labour charges

To check front electrical wiring	50.00	<i>2ol</i>
To check wheel alignment	<i>nn</i> 120.00	X
To remove, refix front undercarriage	<i>nn</i> 250.00	X
To respray painting and etc	800.00	<i>4odl</i>
Panel beating, cut, weld remove & replacing above parts	800.00	<i>4odl</i>
Total Labour	<u>2,020.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,443.30