

EURO SUCCESS SERV PTE. LTD

1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (Ah Huat)

Vehicle No: SMA 8871R

Model: HYUNDAI ELANTRA

Not Authorized
11/10/2014
4 days
H/P: 3600
Ah Huat

QTY	LIST ITEMS	AMOUNT
1	REAR BUMPER <i>70cm</i>	484.20 \$600.00
1	REAR BUMPER LOWER PAD KIT <i>810cm/70cm</i>	241.30 \$290.00
2	REAR BUMPER REFLECTOR L-R @95 <i>N/S 110/5cm</i>	82.50 \$190.00 <i>1PC</i>
2	REAR BUMPER BRACKET L-R @80 <i>11</i>	\$160.00 <i>X</i>
1	REAR BUMPER CLIP @6.50 <i>1set</i>	35.00 \$65.00
1	REAR BUMPER <i>Beam</i>	294.80 \$370.00
1	REAR END PANEL <i>DD/3cm</i>	454.60 \$550.00
1	REAR END PANEL INNER BOARD <i>SC</i>	\$350.00 <i>X</i>
1	REAR BOOTLID <i>DD/3cm</i>	\$950.10
1	REAR BOOTLID GARNISH <i>MS</i>	\$185.60 <i>X</i>
2	REAR BOOT INNER LOCK TOP & BOTTOM LOCK <i>SC</i>	\$255.70 <i>X</i>
1	REAR BOOT LAMP L-R @870 <i>11</i>	\$1,740.00 <i>X</i>
1	REAR BOOT EMBLEM <i>SC</i>	\$50.00 <i>X</i>
1	REAR BOOT LOGO <i>Replaced</i>	\$65.00 <i>X</i>
2	REAR BOOT 'ELANTRA' EMBLEM <i>RE</i>	48.00 \$65.00
2	REAR BOOT 'S' EMBLEM <i>RE</i>	\$45.00
1	REAR BOOT WEATHER STRP <i>1m</i>	\$155.00
1	REAR TAIL LAMP L-H @620.00 <i>one</i>	580.00 $\times 2 = 1160$ \$1,240.00
1	REAR TAIL LAMP BRACKET L-H @125.00 <i>11</i>	\$250.00 <i>X</i>
2	REAR FENDER L-R @950 <i>11</i>	\$1,900.00 <i>X</i>
2	REAR FENDER INNER TRIM BOARD L-R @310 <i>11</i>	\$620.00 <i>X</i>
1	REAR SPARE TYRE BOARD <i>11</i>	\$230.00 <i>X</i>
TOTAL		\$10,326.40
LESS 20%		\$2,065.28
TOTAL		\$8,261.12

SPECIAL NETT ITEMS		
1	REAR license PLATE <i>11</i>	\$55.00 <i>X</i>
1	REAR NUMBER PLATE BOX <i>11</i>	\$120.00 <i>X</i>
1	REAR BUMPER REVERSE SENSOR <i>SC</i>	\$350.00 <i>X</i>
1	REAR BUMPER CLIPS <i>RE</i>	\$55.00 <i>30 S/N</i>
1	REAR BOOT LID INNER SHEILD CLIPS <i>11</i>	\$50.00 <i>X</i>
1	REAR FENDER CLIPS <i>11</i>	\$50.00 <i>X</i>
1	REAR TAIL LAMP CLIPS <i>11</i>	\$30.00 <i>X</i>
TOTAL		\$710.00

LABOUR CHARGES

TO REMOVE AND REFIX REVERSE SENSOR	\$100.00 <i>30</i>
TO REMOVE AND REFIX EXHAUST BOX	11 \$80.00 <i>X</i>
TO REMOVE, REFIT, REPLACE LAMP AND CHECK WIRING	\$80.00 <i>20</i>
TO APPLY UNDERCOATING ON ACCIDENT PARTS	\$450.00 <i>60</i>

To panel beating, replaced parts
AND REPLACE RE-ALIGNMENT ON DAMAGED PARTS
TO putty & spray painting

\$1,500.00 600
\$1000.00 - 600

TOTAL

ESTIMATE PARTS AND LABOUR GRAND TOTAL

12/8/12

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed. Item is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p- 3950.50
202
p- 3060.40
s.n 30
2-1310
4500.4
22
3690