

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO YP 5028H

	REPLACEMENT OF PARTS					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	TAIL LAMP	NOT NECESSARY	\$343.35	\$0.00		
	LESS 25.00% DISCOUNT		(\$85.84)	\$0.00		
			\$257.51	\$0.00		

	Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
1	REAR NUMBER PLATE SUPPORT BRACKET (SPECIAL TYPE) (SN)	NOT NECESSARY	\$160.00	\$0.00	
1	TAIL GATE '60KM STICKER (SN)	NOT NECESSARY	\$20.00	\$0.00	
1	TAIL GATE '23PAX' STICKER (SN)	NOT NECESSARY	\$20.00	\$0.00	
1	TAILGATE WOODEN (SPECIAL TYPE) (SN)	NOT NECESSARY	\$2,500.00	\$0.00	
4	TAILGATE HINGE (SPECIAL TYPE) @\$150.00 (SN)	NOT NECESSARY	\$600.00	\$0.00	
2	TAILGATE SIDE LOCK (SPECIAL TYPE) @\$220.00 (SN)	NOT NECESSARY	\$440.00	\$0.00	
1	REAR HORIZONTAL WOODEN (SN)	TO REPAIR SEE LABOUR	\$1,200.00	\$0.00	
1	REAR STEP PANEL BAR (SN)	NOT NECESSARY	\$950.00	\$0.00	
1	REAR REINFORCEMENT (SN)	NOT NECESSARY	\$1,400.00	\$0.00	
		\$7,290.00	\$0.00		

Labour				
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)	
TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN. INCLUSIVE OF THE REPAIR OF REAR HORIZONTAL WOODEN		\$1,800.00	\$200.00	
TO PUTTY AND SPRAY PAINT		\$1,600.00	\$200.00	
BULB CHECKING, WIRING	NOT NECESSARY	\$150.00	\$0.00	
REAR CHASSIS ALIGNMENT	NOT NECESSARY	\$250.00	\$0.00	
TO REMOVE / REFIX CARGO BED	NOT NECESSARY	\$2,800.00	\$0.00	
REMOVE AND REFIX REAR CANOPY	NOT NECESSARY	\$650.00	\$0.00	
	\$7,250.00	\$400.00		

GRAND TOTAL	\$14,797.51	\$400.00	
RECOMMENDED COST OF REPAIRS		\$400.00	
Report Ref No: CS/AGI24100214/Avn3m4			



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## **LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.