

(08/11/13) W81

ASS. REC. BY:

REF:

CS/A1624100223/Rvp3

4681

T
ASSIGNMENT

From:

Date:

Estimated Cost:

Veh No:

SMF 1999B

Yr Regn: 2018 18GP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMF 1999B

at Workshop m/s

PREMIUM

of

BENEL SECUR

Insured:

A16

Policy No. 1800111858

Claims No. 7081947724SG

Sum Insured:

Excess:

TBA 1200

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

110K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Truck / Trailer or

Make:

AUDIT COMPE 1.8TFSI STONK 1798

Colour

WHITE

AC: Insured / Std / NI / NA

Sp. Reading

61348

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

TRU 222FV831017182

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSV / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/10/24

D.O.I.

15/10/24

Survey held at

BENEL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 60K

25/5/25

Final fig \$56,126.72 confirmed by email (Red 78,613.68, 58%)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

19

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) S + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0781/2024/KS
DATE : 14-Oct-24
WIP : 34375

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SIAW TUNG YENG
ADDRESS : 210 TAGORE AVENUE
SINGAPORE 786225
TELEPHONE : HP +65 98325332
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800111858-06
VEHICLE NO : **SMF 1999 B**
MODEL CODE : AUDI TT COUPE 1.8 TFSI S TRONIC
MODEL YEAR : 28/9/2018
ENGINE NO : CJS 258422
CHASSIS NO : TRUZZZFV8J1017182
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11/10/2024
PLACE OF ACCIDENT : UPPER THOMSON RD & ANG MO KIO AVENUE 1

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1999 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00 /	
2	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00 /	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 X	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00 X	
5	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW FRONTAL AIRBAG, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTYROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIRBAGS.	\$	3,600.00 /	
6	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00 ?	
7	LHS ^{RHS} TO RENEW LHS ^{RHS} FRONT SEAT CUSHION ASSY.	S/N \$	880.00 /	
SUB TOTAL LABOUR CHARGES		:	\$ 7,720.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1999 B.

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
8	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS SILL PANEL AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS SILL PANEL. TO REPAIR RHS FRONT DOOR AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00	2000
9	TO RESPRAY FRONT AND REAR BUMPER, BONNET, RHS FRONT AND REAR FENDER, RHS FRONT DOOR, RHS SILL PANEL, RHS SILL PANEL, RHS SILL PANEL TRIM, ROOF CHANNEL, DOOR ENTRANCE AND DRAIN CHANNEL.	\$ 8,400.00	2750
10	TO REMOVE AND RENEW CENTER AND REAR EXHAUST SILENCERS. TO REALIGN REAR EXHAUST SILENCER.	S/N \$ 480.00	X
11	TO REMOVE AND RENEW FUEL TANK ASSY.	S/N \$ 800.00	X
12	TO RENEW RHS FRONT AND REAR RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 1,040.00	/
13	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	S/N \$ 3,200.00	/
14	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	S/N \$ 3,200.00	/
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 292.00	/
TOTAL LABOUR CHARGES		: \$ 32,332.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>su</i>	1	\$	2,989.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	543.00
3	FRONT BUMPER CLOSING ELEMENT - RH <i>X</i>	1	\$	140.00
4	FRONT BUMPER SECURING STRIP LH / RH <i>?</i>	2	\$	108.00
5	FRONT BUMPER GRILLE - CENTER <i>X</i>	1	\$	202.00
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>de</i>	1	\$	196.00
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>X</i>	1	\$	272.00
8	RADIATOR GRILLE <i>X</i>	1	\$	1,679.00
9	FRONT PARKING AID SENSOR <i>?</i>	1	\$	286.00
10	FRONT PARKING AID SENSOR SEAL RING <i>?</i>	4	\$	11.00
11	FRONT BUMPER GUIDE SECTION <i>?</i>	1	\$	49.00
12	LED HEADLIGHT - RH <i>?</i>	1	\$	9,471.00
13	LIFT CYLINDER - RH <i>X</i>	1		TBC
14	LIFT CYLINDER HOSE <i>X</i>	1	\$	97.00
15	FRONT FENDER - RH <i>renv</i>	1	\$	1,417.00
16	FRONT FENDER ATTACHMENT PARTS - RH <i>X</i>	1	\$	47.00
17	FRONT FENDER BRACE - RH <i>X</i>	1	\$	144.00
18	FRONT FENDER BRACKET - RH UPPER CENTRE <i>X</i>	1	\$	55.00
19	FRONT FENDER BRACKET - RH LOWER <i>X</i>	1	\$	56.00
20	FRONT FENDER CLOSING ELEMENT - RH <i>X</i>	1	\$	53.00
SUB TOTAL SPARE PARTS		:	\$	17,815.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - RH LOWER <i>X</i>	1	\$	56.00
22	FRONT FENDER CLOSING ELEMENT - RH <i>X</i>	1	\$	83.00
23	FRONT FENDER BRACKET - RH LOWER <i>X</i>	1	\$	63.00
24	FRONT FENDER SEAL - RH <i>X</i>	1	\$	47.00
25	FRONT WHEEL HOUSING LINER SEAL - RH <i>X</i>	1	\$	47.00
26	FRONT WHEEL HOUSING LINER - RH <i>at</i>	1	\$	206.00
27	WHEEL HOUSING LINER ATTACHMENT PARTS - RH <i>X</i>	1	\$	125.00
28	FRONT WHEEL SPOILER - RH <i>see</i>	1	\$	141.00
29	AUDI EMBLEM <i>X</i>	1	\$	162.00
30	A-PILLAR FRAME <i>repair</i>	1	\$	3,611.00
31	SILL TRIM STRIP - RH OUTER <i>?</i>	1	\$	316.00
32	SIDE MEMBER TRIM - RH <i>can</i>	1	\$	818.00
33	SIDE MEMBER TRIM ATTACHMENT PARTS - RH <i>m</i>	1	\$	314.00
34	SIDE MEMBER TRIM ADHESIVE TAPES - RH <i>m</i>	1		TBC
35	SIDE MEMBER TRIM BRACKET - RH <i>m</i>	1	\$	25.00
36	REAR WHEEL SPOILER - RH REAR <i>?</i>	1	\$	44.00
37	JACKING POINT BRACKET - RH <i>?</i>	1	\$	81.00
38	UNDERBODY TRIM <i>?</i>	1	\$	303.00
39	NOISE INSULATION <i>?</i>	1	\$	292.00
40	NOISE INSULATION FIXING PARTS <i>?</i>	1	\$	54.00
SUB TOTAL SPARE PARTS		:	\$	6,788.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	UNDERBODY TRIM - RH OUTER ?	1	\$ 155.00	
42	UNDERBODY TRIM - RH REAR ?	1	\$ 94.00	
43	CENTRE SILENCER X	1	\$ 1,178.00	
44	CENTRE SILENCER DUAL CLIP X	1	\$ 70.00	
45	CENTRE SILENCER DUAL CLIP X	1	\$ 70.00	
46	CENTRE SILENCER RETAINER X	1	\$ 51.00	
47	REAR SILENCER X	1	\$ 1,736.00	
48	REAR SILENCER BRACKET - REAR X	2	\$ 107.00	
49	REAR SILENCE CHROME TRIM - LH / RH X	2	\$ 322.00	
50	STEERING WHEEL X	1	\$ 2,971.00	
51	STEERING WHEEL AIRBAG UNIT X	1	\$ 4,597.00	
52	ROOF LINER APPROVED /	1	\$ 1,734.00	
53	ROOF AIRBAG APPROVED /	1	\$ 2,323.00	
54	A-PILLAR TRIM - RH UPPER ?	1	\$ 264.00	
55	C-PILLAR TRIM - RH ?	1	\$ 295.00	
56	DRIVER SEAT BACK LEATHER APPROVED /	1	\$ 4,707.00	
57	DRIVER SEAT PADDING X	1	\$ 533.00	
58	DRIVER SEAT REST LEATHER X	1	\$ 3,044.00	
59	DRIVER SEAT REST PADDING - CENTER X	1	\$ 533.00	
60	DRIVER SEAT REST PADDING - LH / RH X	2	\$ 354.00	
SUB TOTAL SPARE PARTS		:	\$ 25,138.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	SIDE AIRBAG UNIT - RH <i>Act</i>	1	\$	1,900.00
62	SIDE AIRBAG UNIT WIRE HARNESS- RH <i>?</i>	1	\$	238.00
63	SEAT BELT FITTINGS - RH <i>X</i>	1	\$	80.00
64	TRIM PLATE FOR SEAT BELT GUIDE - RH <i>X</i>	1	\$	41.00
65	FUEL TANK <i>X</i>	1	\$	4,404.00
66	ALUMINIUM RIM BOTH RHS AND FRONT LHS <i>bro</i>	3	\$	6,369.00
67	ALUMINIUM RIM RUBBER VALVE <i>u</i>	3	\$	9.00
68	FRONT WISHBONE - RH <i>gbl</i>	1	\$	1,053.00
69	STABILIZER, COMPLETE <i>?</i>	1	\$	479.00
70	FRONT WHEEL BEARING HOUSING - RH <i>?</i>	1	\$	1,196.00
71	FRONT WHEEL HUB - RH <i>?</i>	1	\$	593.00
72	FRONT GUIDE JOINT - RH <i>?</i>	1	\$	225.00
73	FRONT RETAINING PLATE - RH <i>?</i>	1	\$	39.00
74	FRONT COUPLING ROD - RH <i>?</i>	1	\$	112.00
75	AIR GUIDE - RH <i>?</i>	1	\$	56.00
76	FRONT SHOCK ABSORBER - RH <i>?</i>	1	\$	437.00
77	FRONT DRIVESHAFT - RH <i>?</i>	1	\$	1,615.00
78	FRONT WHEEL SPEED SENSOR WIRE HARNESS - RH <i>?</i>	1	\$	256.00
79	FRONT BRAKE HOSE - RH <i>?</i>	1	\$	97.00
80	STEERING RACK <i>?</i>	1	\$	6,431.00
SUB TOTAL SPARE PARTS		:	\$	25,630.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	STEERING TIE ROD - LH / RH <i>X</i> <i>abro</i> ✓	2	\$	372.00
82	STEERING TIE ROD END - LH / RH <i>X</i> <i>bro</i> ✓	2	\$	372.00
83	FRONT SUBFRAME ?	1	\$	1,309.00
84	SUBFRAME BUSHES - UPPER / LOWER ?	1SET	\$	189.00
85	REAR TRACK ROD <i>bt</i> ✓	2	\$	281.00
86	REAR COUPLING ROD ?	1	\$	77.00
87	ANTI-ROLL BAR ?	1	\$	278.00
88	TRACK ROD BRACKET - RH ?	1	\$	168.00
89	REAR AXLE GUIDE - RH ?	1	\$	356.00
90	REAR WISHBONE - RH ?	1	\$	308.00
91	REAR WISHBONE - RH UPPER ?	1	\$	308.00
92	REAR WHEEL BEARING HOUSING - RH ?	1	\$	771.00
93	REAR WHEEL HUB - RH ?	1	\$	593.00
94	STONE CHIP GUARD - RH <i>X</i>	1	\$	12.00
95	REAR SUPPORT FRAME <i>bt</i> ✓	1	\$	1,803.00
96	REAR SHOCK ABSORBER ?	2	\$	729.00
97	REAR WHEEL SPEED SENSOR WIRE HARNESS - RH ?	1	\$	256.00
98	AIR BAG CONTROL UNIT <i>n</i> ✓	1	\$	2,054.00
99	DATA TAG <i>X</i>	1	\$	567.00
100	FRONT SEAT BELT - LH / RH <i>nt</i> ✓	2	\$	2,600.00
SUB TOTAL SPARE PARTS		:	\$	13,403.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
101	REAR SEAT BELT - LH / RH <i>OK</i>	2	\$ 1,344.00	
102	FRONT SEAT BELT ADJUSTER - LH / RH <i>OK</i>	2	\$ 413.00	
103	FRONT NO PLATE <i>X</i>	S/N	\$ 1,500.00	
104	FRONT TYRE - RHS <i>cut / 80%</i>	1	TBC	
105	REAR TYRE - RHS <i>cut / 80%</i>	1	TBC	
106	METAL FILLER POWDER <i>X</i>	S/N	\$ 280.00	
107	ACRYLIC SEALANT <i>X</i>	S/N	\$ 180.00	
108	STONE CHIP <i>X</i>	S/N	\$ 180.00	
109	CAVITY WAX <i>X</i>	S/N	\$ 140.00	
110	SUNDRIES <i>?</i>		\$ 1,500.00	
TOTAL SPARE PARTS		:	\$ 23,352.00	
TOTAL LABOUR CHARGES		:	\$ 32,332.00	
GRAND TOTAL		:	\$ 55,684.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Passer - 4p 9001w68*
: *15/10/24*
: *19 days*
: *EXCESS: TBA*
: *Repair*
: *Res 34 part*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	468I
Vehicle Details	
Vehicle No.:	SMF1999B
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2024
Vehicle Make:	AUDI
Vehicle Model:	TT COUPE 1.8 TFSI S TRONIC
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	CJS258422
Chassis No.:	TRUZZZFV8J1017182
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$45,768.00
Original Registration Date:	28 Sep 2018
First Registration Date:	28 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$56,076.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2028
PARF Rebate Amount:	\$36,449.00
Intended COE Rebate Details	
COE Expiry Date:	27 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,381.00
COE Rebate Amount:	\$13,570.00
Total Rebate Amount:	\$50,019.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 16 Oct 2024

OK