

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0781/2024/KS
DATE : 14-Oct-24
WIP : 34375

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Rasul,

19 Days - Ok - Allan Boo

9-May-25

OWNER'S NAME : MR SIAW TUNG YENG
ADDRESS : 210 TAGORE AVENUE
SINGAPORE 786225
TELEPHONE : HP +65 98325332
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800111858-06
VEHICLE NO : **SMF 1999 B**
MODEL CODE : AUDI TT COUPE 1.8 TFSI S TRONIC
MODEL YEAR : 28/9/2018
ENGINE NO : CJS 258422
CHASSIS NO : TRUZZZFV8J1017182
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11/10/2024
PLACE OF ACCIDENT : UPPER THOMSON RD & ANG MO KIO AVENUE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1999 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	\$ 280.00
3	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND INSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	280.00	
5	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW FRONTAL AIRBAG, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTYROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIRBAGS.	\$	3,600.00	\$ 3,600.00
6	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	
7	TO RENEW LHS FRONT SEAT CUSHION ASSY.	S/N \$	880.00	\$ 880.00
SUB TOTAL LABOUR CHARGES		:	\$ 7,720.00	\$ 5,240.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMF 1999 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
				\$	5,240.00
8	TO REMOVE AND REINSTALL REAR BUMPER. TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS SILL PANEL AND RHS HEADLIHGT. TO CUT OUT AND WELD RHS SILL PANEL. TO REPAIR RHS FRONT DOOR AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	7,200.00	\$	2,000.00
9	TO RESPRAY FRONT AND REAR BUMPER, BONNET, RHS FRONT ANDN REAR FENDER, RHS FRONT DOOR, RHS SILL PANEL, RHS SILL PANEL, RHS SILL PANEL TRIM, ROOF CHANNEL, DOOR ENTRANCE AND DRAIN CHANNEL.	\$	8,400.00	\$	2,750.00
10	TO REMOVE AND RENEW CENTER AND REAR EXHAUST SILENCERS. TO REALIGN REAR EXHAUST SILENCER.	S/N \$	480.00		
11	TO REMOVE AND RENEW FUEL TANK ASSY.	S/N \$	800.00		
12	TO RENEW RHS FRONT AND REAR RIM WITH TYRE AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	1,040.00	\$	1,040.00
13	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	S/N \$	3,200.00	\$	3,200.00
14	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGE AND RENEW ACCORDINGLY.	S/N \$	3,200.00	\$	3,200.00
15	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$	292.00
TOTAL LABOUR CHARGES		:	\$	32,332.00	\$ 17,722.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,989.00	\$	2,391.20
2	FRONT BUMPER FIXING PARTS	1	\$ 543.00		
3	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 140.00		
4	FRONT BUMPER SECURING STRIP LH / RH	2	\$ 108.00		
5	FRONT BUMPER GRILLE - CENTER	1	\$ 202.00		
6	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 196.00	\$	156.80
7	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 272.00		
8	RADIATOR GRILLE	1	\$ 1,679.00		
9	FRONT PARKING AID SENSOR	1	\$ 286.00		
10	FRONT PARKING AID SENSOR SEAL RING	4	\$ 11.00		
11	FRONT BUMPER GUIDE SECTION	1	\$ 49.00		
12	LED HEADLIGHT - RH	1	\$ 9,471.00		
13	LIFT CYLINDER - RH	1	TBC		
14	LIFT CYLINDER HOSE	1	\$ 97.00		
15	FRONT FENDER - RH	1	\$ 1,417.00		
16	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 47.00		
17	FRONT FENDER BRACE - RH	1	\$ 144.00		
18	FRONT FENDER BRACKET - RH UPPER CENTRE	1	\$ 55.00		
19	FRONT FENDER BRACKET - RH LOWER	1	\$ 56.00		
20	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 53.00		
SUB TOTAL SPARE PARTS		:	\$ 17,815.00	\$	2,548.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 2,548.00
21	FRONT FENDER BRACKET - RH LOWER	1 \$	56.00	
22	FRONT FENDER CLOSING ELEMENT - RH	1 \$	83.00	
23	FRONT FENDER BRACKET - RH LOWER	1 \$	63.00	
24	FRONT FENDER SEAL - RH	1 \$	47.00	
25	FRONT WHEEL HOUSING LINER SEAL - RH	1 \$	47.00	
26	FRONT WHEEL HOUSING LINER - RH	1 \$	206.00	\$ 164.40
27	WHEEL HOUSING LINER ATTACHMENT PARTS - RH	1 \$	125.00	
28	FRONT WHEEL SPOILER - RH	1 \$	141.00	\$ 112.80
29	AUDI EMBLEM	1 \$	162.00	
30	A-PILLAR FRAME	1 \$	3,611.00	
31	SILL TRIM STRIP - RH OUTER	1 \$	316.00	
32	SIDE MEMBER TRIM - RH	1 \$	818.00	\$ 654.00
33	SIDE MEMBER TRIM ATTACHMENT PARTS - RH	1 \$	314.00	\$ 250.80
34	SIDE MEMBER TRIM ADHESIVE TAPES - RH	1	TBC	\$ 260.40
35	SIDE MEMBER TRIM BRACKET - RH	1 \$	25.00	\$ 19.84
36	REAR WHEEL SPOILER - RH REAR	1 \$	44.00	
37	JACKING POINT BRACKET - RH	1 \$	81.00	
38	UNDERBODY TRIM	1 \$	303.00	
39	NOISE INSULATION	1 \$	292.00	
40	NOISE INSULATION FIXING PARTS	1 \$	54.00	
SUB TOTAL SPARE PARTS			\$ 6,788.00	\$ 4,010.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 4,010.24
41	UNDERBODY TRIM - RH OUTER	1	\$ 155.00	
42	UNDERBODY TRIM - RH REAR	1	\$ 94.00	
43	CENTRE SILENCER	1	\$ 1,178.00	
44	CENTRE SILENCER DUAL CLIP	1	\$ 70.00	
45	CENTRE SILENCER DUAL CLIP	1	\$ 70.00	
46	CENTRE SILENCER RETAINER	1	\$ 51.00	
47	REAR SILENCER	1	\$ 1,736.00	
48	REAR SILENCER BRACKET - REAR	2	\$ 107.00	
49	REAR SILENCE CHROME TRIM - LH / RH	2	\$ 322.00	
50	STEERING WHEEL	1	\$ 2,971.00	
51	STEERING WHEEL AIRBAG UNIT	1	\$ 4,597.00	
52	ROOF LINER	1	\$ 1,734.00	\$ 1,387.20
53	ROOF AIRBAG	1	\$ 2,323.00	\$ 1,858.40
54	A-PILLAR TRIM - RH UPPER	1	\$ 264.00	\$ 210.80
55	C-PILLAR TRIM - RH	1	\$ 295.00	\$ 236.00
56	DRIVER SEAT BACK LEATHER	1	\$ 4,707.00	\$ 3,765.60
57	DRIVER SEAT PADDING	1	\$ 533.00	
58	DRIVER SEAT REST LEATHER	1	\$ 3,044.00	
59	DRIVER SEAT REST PADDING - CENTER	1	\$ 533.00	
60	DRIVER SEAT REST PADDING - LH / RH	2	\$ 354.00	
SUB TOTAL SPARE PARTS		:	\$ 25,138.00	\$ 11,468.24

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
				\$	11,468.24
61	SIDE AIRBAG UNIT - RH	1	\$ 1,900.00	\$	1,520.00
62	SIDE AIRBAG UNIT WIRE HARNESS- RH	1	\$ 238.00		
63	SEAT BELT FITTINGS - RH	1	\$ 80.00		
64	TRIM PLATE FOR SEAT BELT GUIDE - RH	1	\$ 41.00		
65	FUEL TANK	1	\$ 4,404.00		
66	ALUMINIUM RIM BOTH RHS AND FRONT LHS	3	\$ 6,369.00	\$	5,095.20
67	ALUMINIUM RIM RUBBER VALVE	3	\$ 9.00	\$	7.20
68	FRONT WISHBONE - RH	1	\$ 1,053.00	\$	842.40
69	STABILIZER, COMPLETE	1	\$ 479.00		
70	FRONT WHEEL BEARING HOUSING - RH	1	\$ 1,196.00	\$	956.80
71	FRONT WHEEL HUB - RH	1	\$ 593.00	\$	474.00
72	FRONT GUIDE JOINT - RH	1	\$ 225.00	\$	179.60
73	FRONT RETAINING PLATE - RH	1	\$ 39.00		
74	FRONT COUPLING ROD - RH	1	\$ 112.00	\$	89.60
75	AIR GUIDE - RH	1	\$ 56.00		
76	FRONT SHOCK ABSORBER - RH	1	\$ 437.00	\$	349.20
77	FRONT DRIVESHAFT - RH	1	\$ 1,615.00	\$	1,292.00
78	FRONT WHEEL SPEED SENSOR WIRE HARNESS - RH	1	\$ 256.00		
79	FRONT BRAKE HOSE - RH	1	\$ 97.00		
80	STEERING RACK	1	\$ 6,431.00		
SUB TOTAL SPARE PARTS		:	\$ 25,630.00	\$	22,274.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
				\$	22,274.24
81	STEERING TIE ROD - LH / RH	2 \$	372.00	\$	148.80
82	STEERING TIE ROD END - LH / RH	2 \$	372.00	\$	148.80
83	FRONT SUBFRAME	1 \$	1,309.00	\$	1,047.20
84	SUBFRAME BUSHES - UPPER / LOWER	1SET \$	189.00	\$	150.80
85	REAR TRACK ROD	2 \$	281.00	\$	224.80
86	REAR COUPLING ROD	1 \$	77.00	\$	61.36
87	ANTI-ROLL BAR	1 \$	278.00		
88	TRACK ROD BRACKET - RH	1 \$	168.00	\$	134.40
89	REAR AXLE GUIDE - RH	1 \$	356.00	\$	284.80
90	REAR WISHBONE - RH	1 \$	308.00	\$	246.40
91	REAR WISHBONE - RH UPPER	1 \$	308.00	\$	246.40
92	REAR WHEEL BEARING HOUSING - RH	1 \$	771.00	\$	616.40
93	REAR WHEEL HUB - RH	1 \$	593.00	\$	474.00
94	STONE CHIP GUARD - RH	1 \$	12.00		
95	REAR SUPPORT FRAME	1 \$	1,803.00	\$	1,442.40
96	REAR SHOCK ABSORBER	2 \$	729.00		
97	REAR WHEEL SPEED SENSOR WIRE HARNESS - RH	1 \$	256.00		
98	AIR BAG CONTROL UNIT	1 \$	2,054.00	\$	1,643.20
99	DATA TAG	1 \$	567.00		
100	FRONT SEAT BELT - LH / RH	2 \$	2,600.00	\$	2,080.00
SUB TOTAL SPARE PARTS		:	\$	13,403.00	\$ 31,224.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 1999 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
				\$ 31,224.00
101	REAR SEAT BELT - LH / RH	2	\$ 1,344.00	
102	FRONT SEAT BELT ADJUSTER - LH / RH	2	\$ 413.00	
103	FRONT NO PLATE	S/N	\$ 1,500.00	
104	FRONT TYRE - RHS	1	TBC	\$ 320.00
105	REAR TYRE - RHS	1	TBC	\$ 320.00
106	METAL FILLER POWDER	S/N	\$ 280.00	
107	ACRYLIC SEALANT	S/N	\$ 180.00	
108	STONE CHIP	S/N	\$ 180.00	
109	CAVITY WAX	S/N	\$ 140.00	
	ADD PARTS - SUPPLEMENTARY			\$ 5,754.00
110	SUNDRIES		\$ 1,500.00	\$ 786.72
TOTAL SPARE PARTS			\$ 23,352.00	\$ 38,404.72
TOTAL LABOUR CHARGES			\$ 32,332.00	\$ 17,722.00
GRAND TOTAL			\$ 55,684.00	\$ 56,126.72

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0781/2024/KS 28-Oct-24 GLORY 1 of 1 SMF 1999 B AUDI TT COUPE 1.8 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
<u>PARTS</u>			
1	SIDE PANEL TRIM RHS	\$ 1,041.00	\$ 832.80
2	SIDE PANEL TRIM LHS	\$ 1,041.00	\$ 832.80
3	TRIM PLATE FOR SEAT BELT GUIDE LHS	\$ 31.00	\$ 24.24
4	TRIM PLATE FOR SEAT BELT GUIDE RHS	\$ 31.00	\$ 24.24
5	BRAKE CALIPER CARRIER RHS FRONT	\$ 319.00	\$ 255.20
6	BRAKE DISC RHS FRONT	\$ 232.00	\$ 185.60
7	WHEEL HOUSING LINER RHS REAR	\$ 289.00	\$ 231.20
8	CALLIPER BRACKET RHS REAR	\$ 237.00	\$ 189.20
9	GUIDE PIN	2 \$ 164.00	\$ 130.72
10	1 SET GUIDE BUSHES	\$ 46.00	\$ 36.40
11	BATTERY CENTRAL PROTECTION	\$ 627.00	\$ 501.20
12	SEAT BELT GUIDE RHS	\$ 122.00	\$ 97.20
13	SEAT BELT GUIDE LHS	\$ 122.00	\$ 97.20
14	REAR SEAT BELT - LH / RH	2 \$ 2,600.00	\$ 2,080.00
15	C-PILLAR TRIM - LH	\$ 295.00	\$ 236.00
GRAND TOTAL		\$ 7,197.00	\$ 5,754.00

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT