



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982 Mobile: 91818376		
			Document No. 0				
			Document Date 14/10/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W70J005149		2ZR1832142	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:ECICS TP VEH:SMF3550Z DATE OF ACC:12/10/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				120.00	
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				2880.00	
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				1888.00	
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				97.92	
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				144.00	
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT				288.00	
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				144.00	
9	B	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN				369.60	
10	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN				480.00	
11	1	T52159-68907 PLATE,RR BUMPER	1.00	911.60	30.00	638.12	
12	2	T52462-68010 PAD, RR BUMPER, RH	2.00	7.50	30.00	10.50	
13	3	T52462-68020 PAD, RR BUMPER, RH	2.00	7.50	30.00	10.50	
14	4	S52161-0K040 PIECE, RR BUMPER	8.00	5.80	30.00	32.48	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
					Parts		Less Amount Due
					Labour		
					Sublet		
Lubrication/Fluid							
		Others					

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987				S1000026 / ICECICS		Mr Bek Yong Huat 60 Bayshore Road #25-01 Singapore 469982 Mobile: 91818376			
				Document No. 0					
				Document Date 14/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2016	ZGE20R	HPXNP S6	09/09/2016	SGR3828G	0	33852	79/DS/SGR3828G		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDGG20W70J005149		2ZR1832142	60	Ong Wen Hong	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
15	5	T52575-68020 RETAINER, RR BUMPER				1.00	70.20	30.00	49.14
16	6	T52155-68030 SUPPORT, RR BUMPER				1.00	149.10	30.00	104.37
17	7	T52576-68020 RETAINER, RR BUMPER				1.00	70.20	30.00	49.14
18	8	T52156-68030 SUPPORT, RR BUMPER				1.00	149.10	30.00	104.37
19	9	T58307-68031 PANEL SUB-ASSY, BODY				1.00	817.70	30.00	572.39
20	0	T67935-68020 B0 PLATE, BACK DOOR				1.00	413.40	30.00	289.38
21	1	T67005-68041 PANEL SUB-ASSY, BACK				1.00	2263.80	30.00	1584.66
22	2	T67881-68030 WEATHERSTRIP, BACK				1.00	465.30	30.00	325.71
23	3	T68105-68071 GLASS SUB-ASSY, BACK				1.00	1480.50	30.00	1036.35
24	4	T69350-28151 LOCK ASSY, BACK DOOR				1.00	571.50	30.00	400.05
25	5	T90975-02086 EMBLEM, SYMBOL				1.00	73.50	30.00	51.45
26	6	T75444-68010 PLATE, LUGGAGE COMPT				1.00	56.90	30.00	39.83
27	7	T89997-30070 ANTENNA, ELECTRICAL				1.00	266.20	30.00	186.34
28	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA				2.00	108.00	30.00	151.20
29	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER				1.00	200.00	30.00	140.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature			Charge Summary		Total 12,287.50	
			Please acknowledge receipt of vehicle			Parts 5,775.98		GST 9.00% 1,105.88	
						Labour 6,031.52			
						Sublet 480.00			
						Lubrication/Fluid 0.00		Less 0.00	
						Others 0.00		Amount Due 13,393.38	

Customer Copy