



Supplementary

Estimate No. : **b1 71472**
Date Estimated : **11/10/2024**
Prepared By : **Tee Hong Da**

Page No. :

- ESTIMATE REPAIR FOR -

E.ID Projects Pte Ltd
73 Woodlands Industrial Park E2 Nordix

Singapore 757483

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSI S NO.	REGN. DATE	MODEL	M LEAGE
SKS7878H	WBA70DY0908C03934	28/10/2021	318i Sedan	75175

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To carry out body cavity preservation (x1) (Per panel)	118.00		118.00
* To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function	531.00		531.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET	2.70	10.00	0.00	27.00
# EXPANDING NUT	3.05	2.00	0.00	6.10
# REAR BUMPER RH SIDE GUIDE	143.85	1.00	0.00	143.85
# PLAQUE 74MM	76.55	1.00	0.00	76.55
# GROMMET	0.80	2.00	0.00	1.60

SUPPLEMENTARY ITEMS

Total Labour :	649.00
Total Parts :	255.10
Total Labour & Parts (before GST) :	904.10

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

