

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709672

Date : 14/10/2024

Vehicle Num. : SDZ6677Z

Make/Model : BMW 730LI

Chassis/Eng# : WBA7E02080G245369

Accident Date : 10/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	N/S REAR DOOR	R	3,826.00 X
2.	1PC	N/S REAR DOOR CHROME MOULDING	11	390.00 X
3.	1PC	REAR WINDSCREEN WITH MOULDING	11	1,626.00 X
4.	1PC	N/S REAR FENDER	R	5,258.00 X
5.	1PC	N/S REAR FENDER INNER SHIELD	11	320.00 X
6.	1PC	REAR BUMPER	cut/10,11	2,233.00 /
7.	1PC	N/S REAR BUMPER SIDE RETAINER	11	254.00 X
8.	1PC	REAR BUMPER CHROME MOULDING	11	156.00 /
9.	1PC	N/S REAR RIM	cut	1,500.00 /
10.	1PC	N/S REAR UPPER ARM	11	844.00 X
11.	1PC	N/S REAR UPPER CONTROL ARM	11	577.00 X
12.	1PC	N/S REAR UPPER THRUST ARM	11	565.00 X
13.	1PC	N/S REAR LOWER ARM	11	1,210.00 /
14.	1PC	N/S REAR KNUCKLE ARM	11	1,929.00 /
15.	1PC	N/S REAR WHEEL BEARING	Damage	769.00 /
16.	1 PC	N/S REAR AIR MATIC	11	4,286.00 X
List TotalS\$:				27,837.00
5.00% Discount S\$:				1,391.85
				26,445.15
SPECIAL NETT ITEMS :				
1.	1SET	N/S REAR DOOR INNER TRIM CLIPS	11	40.00 X

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709672

Date : 14/10/2024

Vehicle Num. : SDZ6677Z

Make/Model : BMW 730LI

Chassis/Eng# : WBA7E02080G245369

Accident Date : 10/10/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1PC	REAR WINDSCREEN INNER SEAL		80.00 X
3.	1PC	REAR WINDSCREEN SEALANT		40.00 X
4.	1SET	N/S REAR FENDER INNER SHIELD CLIPS		40.00 X
5.	1SET	REAR BUMPER CLIP		40.00 ✓
6.	1SET	REAR BUMPER RIVET		60.00 X
Special Nett Total S\$:				300.00
LABOUR :				
		TO TRANSFER DOOR GLASS	11	120.00 X
		TO TRANSFER DOOR MECHANISM	11	120.00 X
		TO RESET DOOR CENTRAL LOCKING USING DIAGNOSTIC SCANNER	11	350.00 X
		TO RESET POWER WINDOW	11	350.00 X
		TO REMOVE/REFIT REAR WINDSCREEN GLASS	11	150.00 X
		TO REMOVE/REFIT INNER TRIMS AND GARNISHES	11	350.00 X
		TO TRANSFER AND BALANCE TYRES	11	50.00 X
		TO REPLACE UNDERCARRIAGE		400.00 120
		TO CONDUCT 4 WHEEL ALIGNMENT		120.00 80
		TO CALIBRATE AIR MATIC	11	350.00 X
		TO RUSTPROOF ACCIDENT DAMAGE AREA	11	150.00 X
		TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD		1,200.00 600
		N/S REAR FENDER, REPLACEMENT OF PARTS AND ALIGN THE SAM		1,200.00 600
		TO PUTTY AND SPRAY PAINT ON ACCIDENT DAMAGE AREA		
Labour Total S\$:				4,910.00

E. & O.E.

Total S\$: 31,655.15

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6421.55
5%
P- 6104.65
S.N - 40
L - 1400
7544.65
201
6035