



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 14/10/2024
VEHICLE : SNJ3651H
MAKE/MODEL : TOYOTA PRIUS
CHASSIS NO : ZVW51-6144847
MILLAGE :
TYRE SIZE : 195/65/R15
DOA : 10/10/2024
TP INSURANCE : CHINA TAIPING

Not Authorized
LI Pay 84150/-
Repair After Claim
5 days

List items

01 PC	REAR TAIL GATE	1641.50	PR \$	2,699.41	✓
01 PC	REAR TAIL GATE INNER LOCK		PR \$	395.43	✓
01 PC	REAR TAIL GATE INNER LOCK COVER		\$ PR	19.14	X
01 PC	REAR TAIL GATE CATCH LOCK		\$ PR	48.42	X
01 PC	REAR TAIL GATE WEATHERSTRIP		\$ PR	355.07	X
01 PC	REAR TAIL GATE INNER TRIM BOARD		MY \$	332.04	✓
01 PC	REAR TAIL GATE INNER HANDLE		\$ PR	76.10	X
01 PC	REAR TAIL GATE LH GANISH		\$ PR	65.76	X
01 PC	REAR TAIL GATE OUTER HANDLE		\$ PR	286.30	X
01 PC	REAR TAIL GATE OUTER MOULDING		\$ PR	1,303.29	X
01 PC	REAR TAIL GATE EMBLEM (PRIUS)		NR \$	101.44	X
01 PC	REAR TAIL GATE EMBLEM (HYBRID)		NR \$	106.08	X
01 PC	REAR TAIL GATE EMBLEM (LOGO)		\$ NR	104.60	X
01 PC	REAR LH TAIL GATE LAMP		\$ PR	524.84	X
01 PC	REAR LH LOWER TAIL LAMP		MY \$	494.48	✓
01 PC	REAR LH UPPER TAIL LAMP		\$ PR	733.20	X
01 PC	REAR LH TAIL LAMP BRACKET		\$ PR	85.63	X
01 PC	REAR BUMPER	PR 488.50	PR \$	2,792.23	✓
01 PC	REAR BUMPER DISFUFR		PR \$	460.95	✓
01 PC	REAR BUMPER SIDE RETAINER LH		\$ PR	144.86	✓
01 PC	REAR LH BUMPER SIDE SHEILD		\$ PR	89.56	X
01 PC	REAR REINFORCEMENT		PR \$	563.20	X
01 PC	REAR LH REFELCTOR		MY \$	64.32	✓
01 PC	REAR END PANEL		\$ PR	654.84	✓
01 PC	REAR END PANEL TOP GANISH		PR \$	215.36	✓
01 PC	REAR LH TOP KEY ANTENNA SENSOR		\$ PR	71.48	✓
01 PC	REAR LH LOWER KEY ANTENNA SENSOR		\$ PR	65.04	X
01 PC	REAR END PANEL KEY ANTENNA SENSOR		\$ PR	83.00	X
TOTAL PARTS COST				\$	12,936.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

258

Special Nett Item:

06 PC
10 PC
08 PC
02 PC
01 PC

REAR BUMPER CLIP @ \$6.00
REAR TAIL GATE INNER TRIM BOARD CLIP @ \$6.00
REAR TAIL GATE OUTER GANISH CLIP @ \$6.00
REAR PARKING SENSOR @ \$280
WINDSCEEN SEALANT

Na\$	36.00	✓
na\$	60.00	X
na\$	48.00	X
\$P ₂	560.00	X
na\$	100.00	4012
\$	804.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO DISMANTLE AND REFIX WINDSCREEN & GLASS
6. TO SUPPLY LABOUR TO DIANOGTIS

\$	1,500.00	600l
\$	1,000.00	600l
\$	400.00	30l
\$	200.00	20l
\$	500.00	180l
na\$	300.00	X
\$	3,900.00	
\$	12,936.07	
\$	804.00	
\$	3,900.00	
\$	17,640.07	

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR