



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100241/Dvh3e2
75 BRAS BASAH ROAD	Date:	07/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 2713C	Veh. Inspected	SMY 600H
Policy No.	-	Coverage	0
Claim No.	MT/1298648-002	Excess	\$0.00
Assign From	MARCUS XIAO	Assign Date	14/10/2024

### 2. Vehicle Details

Make & Model	B.M.W. M3	C.C	2979
Engine No.	07229068S55B30A	Year of Reg.	29/06/2015
Chassis No.	WBS3C92010P818164	Colour	GREEN
Odometer	103455 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35R19	BRIDGESTONE	5
L/H Front Tyre	255/35R19	BRIDGESTONE	5
R/H Rear Tyre	285/35R19	BRIDGESTONE	5
L/H Rear Tyre	285/35R19	BRIDGESTONE	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	02/10/2024	Inspection Date	16/10/2024 (11:27)
Survey held at	25 KAKI BUKIT ROAD 4, SYNERGY @ KB, #07-38 SINGAPORE 417800 - REPAIRER: 11 VINYLs		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days