

Century Motors (Singapore) Pte Ltd (Co.Reg.No:192800002R)

6 Marsiling Lane,
Singapore 739145
Tel: 31572626 Email: claims@autoinsure.com.sg

TP INSURER: ECICS Limited (HQ)
CLASSIC ALUMINIUM INDUSTRY PTE LTD
Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/10/2024
Vehicle Reg. No.:	SLU5228A	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN QASHQAI, 1.2 DIG-T CVT (A)	Vehicle Reg. Date:	05/12/2017
Vehicle Colour:	WHITE		
Engine No:	HRA2531244A	Chassis No:	SJNFEAJ11U2121651
Odometer:	91570 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	CENTURY MOTORS (SINGAPORE) PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	12,683.00
Miscellaneous Items	200.00
Labour	3,180.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,063.00
+ GST 9.00% (S\$)	1,445.67
Nett Amount (S\$)	17,508.67

This claim is handled by: LEE SWEE HIAN

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Oct 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Century Motors (Singapore) Pte Ltd/SLU5228A/14/10/2024 17:26	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	0.00	0.00	*550.00 F
2	1		*FRT NUMBER PLATE GANISH	0.00	0.00	*220.00 F
3	1		*HEADLAMP RH	0.00	0.00	*2,400.00 F
4	1		*HEADLAMP LH	0.00	0.00	*2,400.00 F
5	1		*FRT GRILLE TRIM(CHROME)	0.00	0.00	*450.00 F
6	1		*REAR BUMPER	0.00	0.00	*550.00 F
7	1		*REAR BUMPER BRKT RH	0.00	0.00	*110.00 F
8	1		*REAR BUMPER BRKT LH	0.00	0.00	*110.00 F
9	1		*REAR BUMPER LOWER MOULDING	0.00	0.00	-
10	1		*REFLECTOR RH	0.00	0.00	*55.00 F
11	1		*REFLECTOR LH	0.00	0.00	*55.00 F
12	1		*REAR REINFORCEMENT	0.00	0.00	*420.00 F
13	1		*REAR END PANEL	0.00	0.00	*360.00 F
14	1		*TAILGATE	0.00	0.00	*2,400.00 F
15	1		*TAILGATE HINGE RH	0.00	0.00	*50.00 F
16	1		*TAILGATE HINGE LH	0.00	0.00	*50.00 F
17	1		*TAILLAMP RH	0.00	0.00	*270.00 F
18	1		*TAILLAMP LH	0.00	0.00	*270.00 F
19	1		*INNER TAILLAMP RH	0.00	0.00	*250.00 F
20	1		*INNER TAILLAMP LH	0.00	0.00	*250.00 F
21	1		*REAR NUMBER PLATE LIGHT RH	0.00	0.00	*55.00 F
22	1		*REAR NUMBER PLATE LIGHT LH	0.00	0.00	*55.00 F
23	1		*REAR PARKING SENSOR	0.00	0.00	*200.00 F
24	1		*REAR WHEEL ARCH RH	0.00	0.00	-
25	1		*REAR WHEEL ARCH LH	0.00	0.00	-

F=Franchise part.

Sub Total (\$\$)	11,530.00
+ Margin on L,N Items 10.00% (\$\$)	1,153.00
Total Parts (\$\$)	12,683.00

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT BUMPER CLIPS	30.00
2	1	FRT NUMBER PLATE AND HOLDER	40.00
3	1	REAR BUMPER CLIPS	30.00
4	1	REAR NUMBER PLATE AND HOLDER	40.00
5	1	REAR WINDSCREEN SEALANT	60.00
Sub Total (S\$)			200.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,680.00
2	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,200.00
3	TO VACUUM, WAXING & CLEAN INC SUNDRIES	New	150.00
4	LABOUR TO REMOVE AND REFIT REAR WINDSCREEN	New	150.00
Gross Labour Cost (S\$)			3,180.00

Century Motors (Singapore) Pte Ltd/SLU5228A/14/10/2024 17:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >