



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24100247/Enh3e2(N) Date: 07/02/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 8514X	Veh. Inspected	SLS 1034D
	Policy No.		Coverage (\$)	0.00
	Claim No.	BVS24/0737	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	14/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	KMHD841CMJU538300	Colour	BLUE
	Odometer	211810 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45 R17	HANKOOK	5 mm
	L/H Front Tyre	225/45 R17	HANKOOK	5 mm
	R/H Rear Tyre	225/45 R17	HANKOOK	5 mm
	L/H Rear Tyre	225/45 R17	HANKOOK	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/10/2024	Inspection Date	22/10/2024
	Survey held at	WIN AUTOMOTIVE SERVICES PTE LTD 60 JALAN LAM HUAT #04-53 CARROS CENTRE SINGAPORE 737869		
5a. Remarks				
	A)REGISTRATION DATE: 07 SEP 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	