

 $51~\mathrm{UBI~AVE~1,\#01-25~PAYA~UBI~INDUSTRIAL~PARK, SINGAPORE~408933~TEL: (065)~62563561~FAX: (065)~6256431};$

Preliminary Advice

To: Liberty Insurance Pte Ltd Date: 21/11/2024

BVS24/0737 - SLS 1034D

Survey details

Date of loss	11/10/2024
Date of Assignment	14/10/2024
Date of survey	22/10/2024
Location of survey	WIN AUTOMOTIVE SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle Number	SLS 1034D
Make and Model	HYUNDAI ELANTRA
Vehicle Type	SEDAN
Date of Registration	7 Sep 2017
Vehicle Colour	BLUE
Market Value (Est)	\$44,000.00
LTA Rebate	\$21,048.00
Nett Value	\$22,952.00

Proposed/Revised repair cost:

Workshop Estimate	\$9,904.80
Revised Estimate	\$6,067.60
"Check" Items	\$0.00
Total	\$6,067.60
Number of days of repair (Est)	7 Days

Remarks:	The vehicle sustained damages at the rear portion.
	Damages Consistent.
	Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.