

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TP INC
Veron

VEHICLE NO : SLP 1489 R
CHASSIS NO : ZRR800258622

MAKE / MODEL : TOYOTA VOXY
ACCIDENT DATE : 11.10.2024

NO	DESCRIPTION	QTY	AMOUNT (\$\$)
LIST ITEMS			
1	Front bonnet <i>Dented</i>	1	\$ 1345.50
2	Front bonnet moulding <i>cut</i>	1	\$ 408.25
3	Front bonnet side moulding <i>new</i>	1	\$ 92.00
4	Front bonnet inner rubber <i>new</i>	1	\$ 49.45
5	Front bonnet hinge @ \$69.00	2	\$ 138.00
6	Front bonnet lock <i>Dented</i>	1	\$ 145.36
7	Front bonnet lock bracket <i>new</i>	1	\$ 144.55
8	Front grille <i>cracked</i>	1	\$ 1014.65
9	Front grille clips @ \$1.72 <i>new</i>	5	\$ 8.62
10	Front bumper <i>Dented</i>	1	\$ 1843.80
11	Front bumper side holder @ \$117.16 <i>new</i>	2	\$ 234.32
12	Front bumper LH fod lamp	1	\$ 593.40
13	Front bumper LH fod lamp grille <i>Missing</i>	1	\$ 351.67
14	Front bumper LH fod lamp moulding	1	\$ 86.25
15	Front bumper LH fod lamp wire <i>torn</i>	1	\$ 632.50
16	Front bumper centre garnish <i>cut</i>	1	\$ 533.60
17	Front bumper lower grille <i>Dented</i>	1	\$ 300.61
18	Front bumper lower moulding <i>cut</i>	1	\$ 256.91
19	Front bumper inner sponge <i>cracked</i>	1	\$ 138.92
20	Front bumper reinforcement <i>Best</i>	1	\$ 499.79
21	Front bumper LH bracket <i>Dented</i>	1	\$ 86.25
22	Front bumper clips <i>new</i>	1	\$ 5.75
23	Front engine lower cover <i>Dented</i>	1	\$ 176.75
24	Front support panel <i>Broken</i>	1	\$ 2728.49
25	Front centre support panel <i>By Repair</i>	1	\$ 144.55
26	Front LH headlamp <i>Smashed</i>	1	\$ 4935.22
27	Front LH fender <i>Dented</i>	1	\$ 1720.40
28	Front LH fender inner shield <i>new</i>	1	\$ 283.70
29	Front LH fender inner shield clips <i>new</i>	1	\$ 5.75
30	Front LH fender TRD emblm <i>new</i>	1	\$ 66.70
31	Front LH sport rim <i>cut</i>	1	\$ 2232.84
32	Front LH tyre <i>new</i>	1	\$ 437.00
33	Front LH knuckle arm <i>Dented</i>	1	\$ 508.18
34	Front LH knuckle arm bearing <i>Dented</i>	1	\$ 230.69
35	Front LH lower arm <i>Best</i>	1	\$ 1161.50
36	Wiper panel garnish <i>cut</i>	1	\$ 1000.50
37	Wiper panel clips <i>new</i>	1	\$ 5.75
38	Air cleanner hose <i>Dented</i>	1	\$ 174.34
39	Relay fuse box assy <i>cracked</i>	1	\$ 782.00
40	Wiper panel LH side garnish <i>Dented</i>	1	\$ 92.35

Front LH headlamp centre garnish Missing

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

VEHICLE NO : SLP 1489 R
CHASSIS NO : ZRR800258622

MAKE / MODEL : TOYOTA VOXY
ACCIDENT DATE : 11.10.2024

NO	DESCRIPTION	QTY	AMOUNT (\$S)
LIST ITEMS			
41	Front LH headlamp centre garnish <i>ht</i>	1	\$ 163.76 ✓
42	Front bumper inner sensor @ \$207.00 <i>nu</i>	2	\$ 414.00 ✓
43	Front LH wheel housing <i>Reused</i>	1	\$ 780 1203.13 ✓
44	Front LH aircond side garnish <i>Detd</i>	1	\$ 83.83 ✓
45	Front battery <i>Detd</i>	1	\$ 200.00 437.00 ✓
46	Front battery tray <i>Detd</i>	1	\$ 111.43 ✓
47	Front engine lower inner cover <i>corn</i>	1	\$ 204.93 ✓
48	Front resonator <i>Amld</i>	1	\$ 182.85 ✓
			\$ 28397.79
			LESS 25% DICS \$ 7099.45
			TOTAL \$ 21298.34

17839.40
13379.55
S.N: 800

LABOUR COST			
1	Towing fee	1	\$ 150.00 60
2	Remove + reinstall aircond fill in gas	1	\$ 150.00 120
3	Remove + reinstall front LH suspension	1	\$ 400.00 200
4	Remove, replace + repair consistent to the accident	1	\$ 1600.00 1200
5	Respray painting	1	\$ 1200.00 1000
6	To check wiring	1	\$ 200.00 50
7	Tuff kote	1	\$ 100.00 60
			TOTAL \$ 3800.00
			2690
			GRAND TOTAL \$ 24943.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adm LG
1/s 08/24
15/10/24
total 16869.55
1/s: 13.5K
13.5K