



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100291/Aqh3e2
75 BRAS BASAH ROAD	Date:	26/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLR 408X	Veh. Inspected	SKC 6227C
Policy No.	-	Coverage	0
Claim No.	MT/1299387-002	Excess	\$0.00
Assign From	MARCUS XIAO	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200	C.C	1991
Engine No.	27492030450766	Year of Reg.	11/12/2015
Chassis No.	WDD2120342B223784	Colour	BLACK
Odometer	238877 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	265/35 R18	FALKEN	6
L/H Front Tyre	265/35 R18	FALKEN	6
R/H Rear Tyre	265/35 R18	FALKEN	6
L/H Rear Tyre	265/35 R18	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/10/2024	Inspection Date	16/10/2024 (15:44)
Survey held at	KT MOTORWERK 3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE 489978		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days