



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100292/Uqh3e2
75 BRAS BASAH ROAD	Date:	04/11/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 3841M	Veh. Inspected	FBF 2486M
Policy No.	-	Coverage	0
Claim No.	MT/1298429-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	YAMAHA FZ 16	C.C	153
Engine No.	21C5028955	Year of Reg.	08/04/2011
Chassis No.	ME121C052B2029293	Colour	BLUE
Odometer	99999 KM	Steering	DAMAGED
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110-70-17	MITAS	6
L/H Front Tyre			
R/H Rear Tyre	140-70-17	MITAS	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/10/2024	Inspection Date	16/10/2024 (10:54)
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days