



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100294/Uvp3m4
16 RAFFLES QUAY	Date:	24/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6610A	Veh. Inspected	SJX 7298S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009100MFCT	Excess	\$0.00
Assign From	AINI	Assign Date	16/10/2024

2. Vehicle Details

Make & Model	mitsubishi LANCER 1.5 MIVEC SPORTS (A)	C.C	1499
Engine No.	4A910128491	Year of Reg.	07/07/2010
Chassis No.	JMYSRCY2AAU000754	Colour	BLUE
Odometer	220552 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	FALKEN	6
L/H Front Tyre	205/60R16	FALKEN	6
R/H Rear Tyre	205/60R16	FALKEN	6
L/H Rear Tyre	205/60R16	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2024	Inspection Date	17/10/2024
Survey held at	FOCUS AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-50 KAKI BUKIT @ AUTOBAY SINGAPORE 417883		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days