

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Niuc

Name : Sam Wee Kiong (88890648)

Accident Date : 14-Sep-24

Vehicle No : JQS3391 (DOR: 03-03-15)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	\$ 640.00 X
1	Fork under bracket	\$ 225.00 X
1	Front wheel rim	\$ 495.00 X
1	Front rim shaft	\$ 105.00 X
1	Front rim bearing	\$ 88.00 X
1	Front brake disc	\$ 185.00 X
1	Handle bar	\$ 145.00 X
1	Handle-bar ends (1 set)	\$ 125.00
1	Hand grip (1 set)	\$ 90.00 X
1	Handle bar inner bracket	\$ 135.00 X
1	Headlamp assy	\$ 485.00
1	Side mirrors (1 set)	\$ 110.00
1	Front signals (1 set)	\$ 140.00 X
1	Front signal lower garnish	\$ 105.00
1	Front side lower cover	\$ 125.00
1	Basket	\$ 125.00
1	Fairing assy (1 set)	\$ 650.00
1	Front footrest bracket	\$ 65.00
2	Front footrest rubbers	\$ 70.00
1	Gear pedal	\$ 125.00 X
1	Brake pedal	\$ 165.00
1	Rear handle	\$ 225.00
2	Rear footrests	\$ 80.00 X
2	Rear footrest brackets	\$ 156.00 X
		\$ 4,859.00
	Less 10%	\$ 485.90
		\$ 4,373.10

Special Net Items

1	Number plate (1 set)	\$ 38.00 20
2	Fork oils	\$ 30.00 X
2	Fork oil seals	\$ 56.00 X
1	Steering cone (1 set)	\$ 185.00 X
1	Sticket (1 set)	\$ 120.00 60
		\$ 429.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Sam Wee Kiong (88890648)

Accident Date : 14-Sep-24


Vehicle No : JQS3391 (DOR: 03-03-15)

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service (LOD) S\$40.00 <i>refer LOD</i>	\$ -
2	To check wiring and reset headlamp focusing	\$ 17 80.00 X
3	To provide labour	\$ 2 480.00 300
4	To re-align body frame	\$ 17 420.00 X
		\$ 980.00
Grand Total		\$ 5,782.10

Singapore Dollars: Five Thousand Seven Hundred Eighty-Two and Cents: Ten only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: