

TSL AUTO PRO SELECTION PTE LTD

TO	: LIBERTY	DATE	: 15/10/2024
VEHICLE NO	: YQ6691E (2022)	<i>Hui Rong</i>	
VEHICLE MODEL	: TOYOTA DYNA		
CHASSIS NO	: JHHAGV4650K001500		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE LAMP <i>3 MP</i>	1	\$ 69.60	\$ 69.60
2	REAR NUMBER PLATE PANEL <i>3 MP</i>	1	\$ 160.40	\$ 160.40
3	TAILLAMP <i>RT out</i>	2	\$ 285.10	\$ 570.20
4	TAILLAMP PANEL <i>RT in</i>	2	\$ 185.50	\$ 371.00
5	TAILLAMP INNER COVER <i>RT in</i>	2	\$ 121.40	\$ 242.80
6	REAR REFLECTOR <i>3 MP</i>	2	\$ 55.60	\$ 111.20
7	STOPPER BRACKET <i>3 MP</i>	2	\$ 153.20	\$ 306.40
8	TAILGATE <i>Dented</i>	1	\$ 1,680.20	\$ 1,680.20
9	TAILGATE SIDE LOCK <i>Dented</i>	1	\$ 160.50	\$ 160.50
10	TAILGATE HINGE <i>new</i>	2	\$ 65.50	\$ 131.00
11	TAILGATE LOWER PANEL <i>RT in</i>	1	\$ 495.60	\$ 495.60
12	TAILGATE TOYOTA STICKER <i>RT in</i>	1	\$ 167.30	\$ 167.30
13	SPARE TYRE LOCK REGULATOR <i>RT in</i>	1	\$ 283.10	\$ 283.10
14	REAR EXHAUST PIPE <i>3 MP</i>	1	\$ 895.60	\$ 895.60
15	REAR EXHAUST PIPE MOUNTING <i>3 MP</i>	1	\$ 45.10	\$ 45.10
16	REAR EXHAUST PIPE GASKET <i>3 MP</i>	1	\$ 32.40	\$ 32.40

2293.10

1719.82

TOTAL PRICE:

LESS 25%

SUB TOTAL PRICE:

\$ 5,722.40

\$ 1,430.60

\$ 4,291.80

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 30.00	\$ 30.00
2	REAR BUMPER <i>Best</i>	1	\$ 1,200.00	\$ 1,200.00
3	REAR BUMPER STICKER <i>in</i>	1	\$ 100.00	\$ 100.00
4	REAR STEP BRACKET <i>Best</i>	1	\$ 200.00	\$ 200.00
5	REVERSE SENSOR (SET) <i>new</i>	1	\$ 280.00	\$ 280.00
6	STOPPER <i>RT in</i>	2	\$ 40.00	\$ 80.00
7	TAILGATE INNER ALUMINIUM PLATE <i>Best</i>	1	\$ 500.00	\$ 500.00
8	TAILGATE INNER ALUMINIUM PLATE RIVETS <i>in</i>	1 SET	\$ 50.00	\$ 50.00
9	DYNA STICKER <i>3 MP</i>	1	\$ 45.00	\$ 45.00
10	70KM/H STICKER <i>3 MP</i>	1	\$ 15.00	\$ 15.00
11	13 PAX STICKER <i>3 MP</i>	1	\$ 15.00	\$ 15.00
12	FLOOR PANEL TOP ALUMINIUM PLATE <i>3 MP</i>	1	\$ 800.00	\$ 800.00
13	FLOOR PANEL TOP ALUMINIUM PLATE RIVETS <i>3 MP</i>	1 SET	\$ 100.00	\$ 100.00

TOTAL :

\$ 3,415.00

1785

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	30	
5	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
		TOTAL \$	2,650.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 7,706.80

TOTAL LABOUR COST: \$ 2,650.00

TOTAL REPAIR COST: \$ 10,356.80

1910

Total: 4614.82

L/S: 3.7K

04 Days

3.7K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S: 3/1/10