

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 25 Oct 2024

**Preliminary Advice**

Vehicle No	: SLC3277R	Accident Date	: 12/10/2024
Make	: MERCEDES-BENZ E200 KOMPRESSOR	Policy No.	: MPC24A00127000
Assignment Date	: 16/10/2024	Excess	: S\$1,000.00
Date of Inspection	: 17/10/2024	Est. Duration of Repair	: 8
Inspection At	: CONVERGENCE AUTOMOTIVE PTE LTD (HQ) 39 WOODLANDS CLOSE, MEGA@WOODLANDS #01-24 SINGAPORE 737856		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,750.50	(Estimate \$22,694.50 + Supplementary \$1,056.00)
Revised Amount	:S\$	13,273.50	(Inclusive of supplementary)
Check Items (Estimated)	:S\$	2,376.00	
Total	:S\$	15,649.50	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	13,452.00
Salvage Value	:S\$	
Margin for Repair	:S\$	31,548.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.