



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100306/Uvh3e2
75 BRAS BASAH ROAD	Date:	23/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 1565T	Veh. Inspected	SLZ 2908P
Policy No.	-	Coverage	0
Claim No.	MT/1300125-001	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	17/10/2024

2. Vehicle Details

Make & Model	HONDA VEZEL (A)	C.C	1496
Engine No.	L15B3521767	Year of Reg.	30/06/2015
Chassis No.	RU11021752	Colour	WHITE
Odometer	191899 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	MICHELIN	6
L/H Front Tyre	215/55R17	MICHELIN	6
R/H Rear Tyre	215/55R17	MICHELIN	6
L/H Rear Tyre	215/55R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/10/2024	Inspection Date	18/10/2024 (11:08)
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days