

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035962
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page: 1 of 2
Your ref.: DHOM110162271803
Job No.: 74772
Our ref.: 23.10.17
Payment
Date: 16/10/2024

Attn

Vehicle No: SFF 6263R
Vehicle Model : Lexus ES250
Accident on ...: 15/10/2024

Not Insured
Runway B4 part
Ex TAA @ 4816.00
2 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front bumper	420.00		420.00 ✓
1.00	Pc	Front bumper upper rubber seal	45.00		45.00 ✓
1.00	Pc	Front number plate base	70.00		70.00 ✓
1.00	Pc	Front radiator grille	450.00		450.00 ✓
1.00	Pc	Front radiator grille surround chrome	175.00		175.00 ✓
1.00	Pc	Front bumper sponge	60.00		60.00 ✓
1.00	Pc	Front tow hook cover	40.00		40.00 ✓
1.00	Pc	Front bumper lower centre grille	250.00		250.00 ✓
1.00	Pc	Front bumper lower centre grille chrome moulding	250.00		250.00 ✓
Total amount of parts supplied - \$1,760.00					
1.00		10% of parts supplied	176.00		176.00
Special Nett Item:					
1.00		Front number plate	40.00		40.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0035962
United Overseas Insurance Ltd
146 Robinson Road
#02-01 UOI Building
Singapore 068909

Page: 2 of 2
Your ref.: DHOM110162271803
Job No.: 74772
Our ref: 23.10.17
Payment:
Date: 16/10/2024

Attn

Vehicle No ...: SFF 6263R
Vehicle Model : Lexus ES250
Accident on ...: 15/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Labour & Misc:					
1.00		To check/clear fault codes after repair	80.00		80.00 80
1.00		To dismantle+renew above parts	250.00		250.00 220
1.00		To respray paint	250.00		250.00 ✓

Sub-Total 2,556.00
GST 9.00% 230.04
Total S\$ 2,786.04

本公司拥有最先进的 CARLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CARLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."