

ASS. REC. BY:

REF: CS/ICS24100309/Rq p3

0582

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SPT 71C

at Workshop m/s PERFORMANCE

of ALEXANDRA RD

Insured: ICS

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 128k
IDAC Accident Rpt: Consistent?: **Yes or No**
GIA / PR Seen: Consistent?: **Yes or No**
Est. Repairs: 7 days Res.: **Yes or No**
Lum Sum: % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ **Person Contacted:** _____

Veh No: SFT 77C Yr Regn: 2016 / NOV
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: B-M. W M235I Comp C.C. 2979
Colour: BLUE AC: Insured / Std / Nil / NA
Sp. Reading: 126011 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: WB41J720 V4863
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD / Rim or _____
Tyre Size: F: 24.5/35ZR18
R: _____

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO or

Front
R/Bal. 6 mm
L/Bal. 6 mm
D.O.A. 13/10/24
Survey held at

Rear
R/Bal. 6 mm
L/Bal. 6 mm
D.O.I. 24/10/24
ALEXANDRA

Des. of Damages: Frt / Rear / ORS / N/S / WC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
-------------	----------------------

REPAIR LIMIT - 87K

finalised final fig \$13471.75, 7 days (Red \$1864.40, 14%)

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) 30/12 Typist

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) : \$ + RS \$

☐ Interview (S) Photos

□	: Tech. Invs (\$	)	Others
---	------------------	---	--------

: Weekend (\$)

Report Format : MER-TP

~~Lump Sum / I.B.I:~~ (\$ 13471.75

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71503
Date Estimated : 15/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chua Ai Swan
3 Elliot Walk

Singapore 458658

- ACCOUNT - 144674

ECICS Limited
10 Eunos Road 8
Singapore Post Centre #09-04A
Singapore 408600

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT77C	WBA1J72070V486863	29/11/2016	M235i COUPE	121570

DESCRIPTION

To replace rear bumper, front rh door, side sill rh, attachments and make good of rear rh fender.

VALUE

5,100.00

To painting rear bumper, rear rh fender, door rh and side sill rh.

3,940.00

To check electrical wiring system and lighting at the rear section for proper function.

177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

177.00

To replace tyre and wheel rim including balancing. (1x).

94.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

531.00

To carry out body cavity preservation. (Per panel).

118.00

Sundries.

150.00

Total Labour 1: 10,287.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7.5X18 M DOUBLE SPK 436 cut ✓	1	1,139.35	1,139.35
FRT RH DOOR bt ✓	1	1,479.50	1,479.50
RH SIDE GUIDE FOR BUMPER? at ✓	1	164.40	164.40
REAR BUMPER PANEL PRIMED (M)	1	1,109.90	1,109.90
FRT RH OUTSIDE DOOR CHANNEL SEALING m ✓	1	114.40	114.40
FRT RH DOOR JOINT SEAL m ✓	1	87.75	87.75
RH SILL STRIP PRIMED (M) de ✓	1	386.20	386.20
RH HOLDING STRIPS SET (M) m ✓	1	128.35	128.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg No 197401559W GST Reg No M2-0020081-X
Tel: Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 71503
Date Estimated : 15/10/2024
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFT77C	WBA1J72070V486863	29/11/2016	M235i COUPE	121570

Total Parts : 4,609.85

Claims OD / Ord Party Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 24/10/24 Excess S\$ _____

Surveyor's Name Rasul Sign _____

Surveyor's Tel 96010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

Res 58 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



Labour 1	:	10,287.00
Parts	:	4,609.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	1,340.72
Grand Total	:	16,237.57

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

058Z

Vehicle No.:

Vehicle to be Exported:

SFT77C

Intended Deregistration Date:

No

Vehicle Make:

24 Oct 2024

Vehicle Model:

B.M.W.

Primary Colour:

M235I COUPE A/T ABS D/AB 2WD DSC HID NAV

Manufacturing Year:

Blue

Engine No.:

2016

Chassis No.:

06579534N55B30A

Maximum Power Output:

WBA1J72070V486863

Open Market Value:

240.0 kW (321 bhp)

Original Registration Date:

\$39,678.00

First Registration Date:

29 Nov 2016

Transfer Count:

29 Nov 2016

Actual ARF Paid:

0

Intended PARF Rebate Details

\$47,550.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Nov 2026

PARF Rebate Amount:

\$28,530.00

Intended COE Rebate Details

COE Expiry Date:

28 Nov 2026

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$55,201.00

COE Rebate Amount:

\$11,561.00

Total Rebate Amount:**\$40,091.00****Message**

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 24 Oct 2024

OK



BMW M235i Coupe

\$95,000 Instalment \$4,294/mth

PREMIUM AD

Apply for 2.48% loan

Shortlist

Get Warranty

TRENDING NOW

mycarforum

Mercedes Owners Thread

Overview Financial Photo Research

Depreciation	<i>i</i> \$49,900 / year
Reg. Date	31-Mar-2016 (1yr 5mths 5days COE left)
Manufactured	<i>i</i> 2016
Mileage	110,000 km (12.8k / year)
Transmission	Auto
Engine Cap	2,979 cc
Road Tax	<i>i</i> \$2,362 / year
Power	240.0 kW (321 bhp)
Curb Weight	<i>i</i> 1,470 kg
COE	<i>i</i> \$48,002
OMV	<i>i</i> \$39,678
ARF	<i>i</i> \$47,550
Dereg Value	<i>i</i> \$32,941 as of today
No. of Owners	<i>i</i> 4
Type of Veh	Sports Car