

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBQ3664B model honda adv 750

Number Plate	SN	45	305/2
Number Plate Lamp	CR	260	—
Rear Mudguard	D's	155	—
Reflector	CNA	48	—
Rear RH Signal	SVC	125	X
Cover Signal	TM	55	—
Cover Mudguard	D's	135	—
Cover Mudguard Silver	11	88	X
Cover Mudguard Lower	TM	135	X
Mudguard Bracket	D's	380	—
Camera	multifunction	350	SN
Box 55L	11	280	X
Engine Guard	11	380	X
Side Stand	11	150	X
Mirror	11	80	X
Balancer	11	25	X
LH Lever	11	45	X
Alignment	11	300	X
Towing	11	50	X
Labour		450	180
Total		3536	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-1198
102
107820
380
180
16382
202
1310.

not Acknowledged
in
merch
18/10/24
1/5 \$1300
take 3 days