



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100322/Evh3e2
75 BRAS BASAH ROAD	Date:	28/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNS 5273E	Veh. Inspected	SNF 1359L
Policy No.	-	Coverage	0
Claim No.	MT/1299542-002	Excess	\$0.00
Assign From	ENG HUEY HUEY	Assign Date	18/10/2024

2. Vehicle Details

Make & Model	HYUNDAI AE IONIQ	C.C	1580
Engine No.	G4LENU218533	Year of Reg.	04/05/2022
Chassis No.	KMHC851CVNU290072	Colour	BLACK
Odometer	201841 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65 R15	FIRENZA	5
L/H Front Tyre	195/65 R15	FIRENZA	5
R/H Rear Tyre	195/65 R15	FIRENZA	5
L/H Rear Tyre	195/65 R15	FIRENZA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/10/2024	Inspection Date	18/10/2024 (11:22)
Survey held at	8 KAKI BUKIT AVENUE 4 #08-19 PREMIER @ KAKI BUKIT SINGAPORE 415875 - REPAIRER: MIRAI AUTO PERFORMANCE PTE LTD		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days