



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: RAJESWARY

Ref: CS/INC24060223/Aqh3m4(N)

Date: 26/08/2025

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLC 3J	<b>Veh. Inspected</b>	SNR 705P
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1282756-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HAZALYSA BINTE IBRAHIM	<b>Assign Date</b>	24/06/2024

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA NOAH HYBRID	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2024
<b>Chassis No.</b>	ZWR900159301	<b>Colour</b>	BLACK
<b>Odometer</b>	6743 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	205/60R16	DUNLOP	6 mm
<b>L/H Front Tyre</b>	205/60R16	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	205/60R16	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	205/60R16	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	20/06/2024	<b>Inspect Date / Time</b>	25/06/2024 ( 01:08 PM )
<b>Survey held at</b>	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>12 Working Days</b>
--	------------------------