

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24100336/ANP3E2  
**Date:** 24/10/2024REFERENCE

Insured/Claimant:	TAN POH KHIANG	Policy No:	2100488778	
Date of Loss:	18/10/2024	Nature of Claim:	OD	Claim No: 4246402144SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLJ136Y</b>		
Make & Model:	AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A)	Engine No:	CVN017691
Reg. Date:	31/10/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF49HA026658
Colour:	Grey	Odometer:	91695 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$44,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	24/10/2024	
Date Inspected:	22/10/2024	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	0.0 days	

**Adjuster:** ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(FOR MANDATE ONLY)

**TOTAL LOSS ASPECT**

Market Value :	\$44,000.00
OMV :	\$32,161.00
PARF Rebate (1) :	\$16,215.00
Quota Premium Paid :	\$56,340.00
COE Rebate (2) :	\$11,374.00
Total Rebate (1) + (2) = :	\$27,589.00

The total amount incurred will be Market Value \$44,000.00 minus Total Rebate \$27,589.00 = \$16,411.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**