



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100338/Uqp3e2
16 RAFFLES QUAY	Date:	06/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 9877K	Veh. Inspected	SNH 8664Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009201MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	21/10/2024

### 2. Vehicle Details

Make & Model	LEXUS RC F COUPE (A)	C.C	4969
Engine No.	2UR2058889	Year of Reg.	12/06/2015
Chassis No.	JTHHP5BC605003165	Colour	BLUE
Odometer	78667 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/35R19	MICHELIN	6
L/H Front Tyre	255/35R19	MICHELIN	6
R/H Rear Tyre	285/35ZR19	MICHELIN	6
L/H Rear Tyre	285/35ZR19	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/10/2024	Inspection Date	18/11/2024
Survey held at	SPECIALISTS MOTOR PTE LTD - BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days