

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)59 Loyang Drive
Singapore 508969
Tel: 6214 8300**TP INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	19/10/2024
Vehicle Reg. No.:	SHD3856L	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ, 1.6 (A)	Vehicle Reg. Date:	11/12/2018
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU131993	Chassis No:	KMHC851CVKU121806
Odometer:	773629 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,235.36
Miscellaneous Items	12.00
Labour	1,480.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,727.36
+ GST 9.00% (S\$)	515.46
Nett Amount (S\$)	6,242.82

This claim is handled by: LOKE WEI YIENG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2024)
 Parts: 143 HYUNDAI IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHD3856L/21/10/2024 10:58
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER COVER / BR	20.00	0.00	*481.10 FL
2	1		*FRT BUMPER CLIPS / MC	20.00	0.00	*22.00 FL
3	1		*FRT BUMPER SIDE BRACKER RH / BR	20.00	0.00	*28.00 FL
4	1		*FRT BUMPER MOULDING CENTRE UPPER X	20.00	0.00	*368.50 FL
5	1		*HEADLAMP RH	20.00	0.00	*2,110.30 FL
6	1		*FRT BUMPER SIDE MOULDING RH / BR	20.00	0.00	*186.90 FL
7	1		*DAYLIGHT RH	20.00	0.00	*642.50 FL
8	1		*HEADLAMP SUPPORT PANEL	20.00	0.00	*907.30 FL
9	1		*FRT WHEEL HUB CAP RH X	20.00	0.00	*346.40 FL
10	1		*FRT FENDER SHIELD RH X	20.00	0.00	*174.60 FL
11	1		*EMBLEM- BLUE DRIVE RH / MC	20.00	0.00	*26.60 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

5,294.20

- List Item Discount on L Items (S\$)

1,058.84

Total Parts (S\$)

4,235.36

ComfortDelGro Engineering Pte Ltd/SHD3856L/21/10/2024 10:58. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)			12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New 380	800.00
2	SPRAY PAINTING CHARGE	New 560	600.00
3	CHECK ALL LIGHTING	New 30	80.00
Gross Labour Cost (S\$)			1,480.00

ComfortDelGro Engineering Pte Ltd/SHD3856L/21/10/2024 10:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve (LKK)
21/10/24, 3:30 pm
w n
2/5
by AL sy
3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: