

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 24 Oct 2024

**Preliminary Advice**

Vehicle No	: SMH9299A	Accident Date	: 21/10/2024
Make	: TOYOTA PRIUS PLUS	Policy No.	: MPC23A00367800
Assignment Date	: 22/10/2024	Excess	: S\$0.00
Date of Inspection	: 21/10/2024	Est. Duration of Repair	: 10
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,773.56 (incl.supplementary \$506.40)
Revised Amount	:S\$	24,965.24
Check Items (Estimated)	:S\$	11,524.31
Total	:S\$	36,489.55 (incl.supplementary \$506.40)
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	84,000.00
COE / PARF Rebate	:S\$	29,800.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,200.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Kindly approved on the supplementary