



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600			S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851		
			Document No. 0				
			Document Date 21/10/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC23A00367800 ACC DATE:21/10/2024 TOW/DRIVE IN:DRIVE IN EXCESS: DATE-IN:21/10/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				180.00	
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				3456.00	
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				3304.00	
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				97.92	
6	B	BP-MECH2 TO REMOVE AND REPLACE A/C CONDENSER & RA DIATOR				288.00	
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				144.00	
8	B	BP-WS2 TO REMOVE AND INSTALL FRONT WINDSCREEN				369.60	
9	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR FRONT WINDSCREE N				480.00	
10	S	BP-SUBLET TO SUPPLY FRONT NUMBER PLATE				80.00	
11	1	T11212-37090 COVER, CYLINDER	1.00	279.50	30.00	195.65	
12	2	T16400-37290 RADIATOR ASSY	1.00	2979.00	30.00	2085.30	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunus Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851
	Document No. 0	
	Document Date 21/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU90J035158	2ZR0C68145	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	3	T16361-37020 FAN	1.00	390.80	30.00	273.56
14	4	T16361-37010 FAN	1.00	303.30	30.00	212.31
15	5	L16711-37040 SHROUD, FAN	1.00	411.10	30.00	287.77
16	6	T16712-37051 SHROUD, FAN, NO.2	1.00	167.10	30.00	116.97
17	7	UG9010-47050 RADIATOR ASSY	1.00	1299.50	30.00	909.65
18	8	T17120-37054 MANIFOLD ASSY,	1.00	1437.50	30.00	1006.25
19	9	T17750-37070 INLET ASSY, AIR	1.00	335.10	30.00	234.57
20	0	T17700-37252 CLEANER ASSY, AIR	1.00	1582.40	30.00	1107.68
21	1	T17882-37040 HOSE, AIR CLEANER,	1.00	82.40	30.00	57.68
22	2	T17894-37010 RESONATOR, INTAKE	1.00	97.30	30.00	68.11
23	3	T17881-37120 HOSE, AIR CLEANER,	1.00	82.40	30.00	57.68
24	4	T52119-47969 COVER, FR BUMPER	1.00	855.40	30.00	598.78
25	5	T53395-47030 SEAL, HOOD TO FR END	1.00	141.40	30.00	98.98
26	6	T52115-47030 SUPPORT, FR BUMPER	1.00	104.50	30.00	73.15
27	7	T52116-47030 SUPPORT, FR BUMPER	1.00	104.50	30.00	73.15
28	8	T52821-47020 DUCT, AIR INTAKE, RH	1.00	178.90	30.00	125.23
29	9	T52822-47020 DUCT, AIR INTAKE, LH	1.00	178.90	30.00	125.23
30	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.80	30.00	40.60
31	1	T53102-47180 GRILLE SUB-ASSY,	1.00	789.60	30.00	552.72
32	2	T52112-47020 EXTENSION, FR	1.00	46.00	30.00	32.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600				S1000026 / ICECICS		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851			
				Document No.					
				0					
				Document Date					
				21/10/2024					

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU90J035158	2ZR0C68145	60	Ong Wen Hong	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
33	3	T52113-47020 EXTENSION, FR	1.00	47.30	30.00	33.11
34	4	T53113-47060 GRILLE, RADIATOR,	1.00	207.40	30.00	145.18
35	5	T52611-47100 ABSORBER, FR BUMPER	1.00	110.20	30.00	77.14
36	6	T52021-47160 REINFORCEMENT	1.00	1010.00	30.00	707.00
37	7	T52618-47060 ABSORBER, FR BUMPER,	1.00	205.10	30.00	143.57
38	8	T53111-47110 GRILLE, RADIATOR	1.00	672.20	30.00	470.54
39	9	S52161-0K040 PIECE, RR BUMPER	8.00	5.80	30.00	32.48
40	0	T53301-47070 HOOD SUB-ASSY	1.00	1277.10	30.00	893.97
41	1	T53341-47030 INSULATOR, HOOD	1.00	570.00	30.00	399.00
42	2	T53801-47100 FENDER SUB-ASSY, FR	1.00	1400.50	30.00	980.35
43	3	T53866-47030 SEAL, FR FENDER TO	1.00	34.20	30.00	23.94
44	4	T53825-47020 PROTECTOR, FR	1.00	60.80	30.00	42.56
45	5	T53827-47040 PROTECTOR, FR FENDER	1.00	156.70	30.00	109.69
46	6	T53875-47061 LINER, FR FENDER, RH	1.00	262.80	30.00	183.96
47	7	T53510-47121 LOCK ASSY, HOOD	1.00	187.20	30.00	131.04
48	8	T53410-47160 HINGE ASSY, HOOD, RH	1.00	81.80	30.00	57.26
49	9	T53420-47160 HINGE ASSY, HOOD, LH	1.00	81.80	30.00	57.26
50	0	T53201-47050 SUPPORT SUB-ASSY,	1.00	2033.60	30.00	1423.52
51	1	T53293-47050 DEFLECTOR, RADIATOR	1.00	120.00	30.00	84.00
52	2	T53294-47040 DEFLECTOR, RADIATOR	1.00	110.80	30.00	77.56

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600	S1000026 / ICECICS	Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851
	Document No. 0	
	Document Date 21/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU90J035158	2ZR0C68145	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
53	3	T53289-47041 COVER, RADIATOR	1.00	190.30	30.00	133.21
54	4	T56101-4F914 GLASS SUB-ASSY,	1.00	2237.60	30.00	1566.32
55	5	T75533-47060 MOULDING,	1.00	84.10	30.00	58.87
56	6	L56117-50140 DAM, WINDOW GLASS	1.00	40.10	30.00	28.07
57	7	L56115-30100 STOPPER, WINDSHIELD	1.00	6.40	30.00	4.48
58	8	T56116-22050 STOPPER, WINDSHIELD	1.00	6.20	30.00	4.34
59	9	T55708-47150 LOUVER SUB-ASSY,	1.00	916.70	30.00	641.69
60	0	T55820-47010 VENTILATOR ASSY,	1.00	59.10	30.00	41.37
61	1	T75310-33050 EMBLEM ASSY,	1.00	146.80	30.00	102.76
62	2	T81140-47660 UNIT ASSY, HEADLAMP,	1.00	3890.00	30.00	2723.00
63	3	T81070-47660 UNIT ASSY, HEADLAMP,	1.00	3890.00	30.00	2723.00
64	4	T52125-47010 EXTENSION, FR BUMPER	1.00	105.50	30.00	73.85
65	5	T52126-47010 EXTENSION, FR BUMPER	1.00	105.50	30.00	73.85
66	6	T81210-47010 LAMP ASSY, FOG, RH	1.00	473.20	30.00	331.24
67	7	T81220-47010 LAMP ASSY, FOG, LH	1.00	449.90	30.00	314.93
68	8	T81430-47050 LAMP ASSY, DAYTIME	1.00	895.00	30.00	626.50
69	9	TG9200-29015 INVERTER ASSY,	1.00	5976.10	30.00	4183.27
70	0	TG9110-47030 BRACKET ASSY,	1.00	422.60	30.00	295.82
71	1	T85315-47221 JAR, WASHER, A	1.00	303.30	30.00	212.31
72	2	T85319-47220 PIPE, WASHER, A	1.00	92.90	30.00	65.03

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	Amount Due
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No. S1000026 / ICECICS		Customer Details			
ECICS Limited 10 Eunos Road 8 #13-06 Singapore 408600			Document No. 0		Mr Tan Hock Hai 322A Jurong East Street 31 #04-270 Singapore 601322 Mobile: 96883851			
			Document Date 21/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ZVW40R	AWXEBW S2	18/12/2018	SMH9299A	0	34006	79/OD/SMH9299A	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZS3EU90J035158		2ZR0C68145	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
73	3	T86510-48070 HORN ASSY, HIGH			1.00	186.60	30.00	130.62
74	4	T88460-47170 CONDENSER ASSY			1.00	2170.80	30.00	1519.56
75	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00	30.00	151.20
76	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00	30.00	140.00
77	7	S08889-80102 COOLANT,SLLC&&&			2.00	108.00		216.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 39,267.16		
		Please acknowledge receipt of vehicle		Parts 30,767.64		GST 9.00% 3,534.04		
				Labour 7,939.52				
				Sublet 560.00				
				Lubrication/Fluid 0.00		Less 0.00		
				Others 0.00		Amount Due 42,801.20		

Customer Copy