

SMRT Accident Vehicle Repair Estimates

SMRT Author
60 Woodland
FAX Number
Estimator Te
Accident Rep


Date Generated

User ID

Section A - Accident Details

Registration Number	SHB5616K
Case Reference Number	TAX/10/24/2046
Registration Date	1/12/2020
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	LIU MENG LYE
Type of Accident	Side Swipe
Accident Date and Time	16/10/2024 1:15 PM
Accident Reported Date and Time	16/10/2024 1:39 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24100065
Special Instruction to ARC, if any	TP/AIG - LKK
Prepared Date and Time	22/10/2024 10:30 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$0.00
Total Spray Cost	\$756.00	\$0.00
Total Spare Part Cost	\$2,865.43	\$0.00
Total Other Cost	\$380.00	\$0.00
TOTAL COST	\$4,677.43	\$0.00
Lump Sum Total	\$4,700.00	\$0.00
Number of Repair Days	5.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	22/10/2024 10:36 AM	
Signature		<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodlanc
FAX Number
Estimator Te
Accident Rep

Date Genera

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicab
TO REPAIR RH FRONT PORTION	\$676.00	200
Total Labour	\$676.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO RESPRAY FRONT BUMPER	\$378.00	200
TO RESPRAY FRONT FENDER RH	\$378.00	200
Total Spray Painting & Panel Beating	\$756.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicab
TO WASH AND VACUUM	\$60.00	x nn
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	30 nec
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	20 nec
TO REPLACE SUNDRY PARTS	\$100.00	x nn
Total Other Costs	\$380.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		52119-47980	COVER, FR BUMPER	1.00	\$565.60	25.00	\$424.20	Replace	x Repair
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$86.20	25.00	\$64.65	Replace	x nn
		52161-16010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	x nn
		52712-47040	MOULDING, FRONT BUMPER SIDE, RH	1.00	\$103.70	25.00	\$77.78	Replace	x nn
		81145-47890	UNIT , HEADLAMP , RH	1.00	\$2,852.40	25.00	\$2,139.30	Replace	x nn
		53801-47080	FENDER SUB-ASSY, FR , RH	1.00	\$1,060.70	25.00	\$795.53	Replace	x Repair
		75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$59.10	25.00	\$44.33	Replace	/ nec
		53875-47120	LINER, FR FENDER, RH	1.00	\$219.10	25.00	\$164.33	Replace	x nn
Total					\$4,951.60		\$3,745.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Cl
Total									

Steve (LKK)
 22/10/24, 4.00 pm
 Without Prejudice
 P/P (No part giving)
 2 days