



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

<b>Account Details</b>		<b>Account No.</b>	<b>Customer Details</b>	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Ms Julis Tng Sok Luan 672A Klang Lane #08-109 Singapore 211672  Mobile: 91854912	
		<b>Document No.</b>		
		0		
		<b>Document Date</b>		
		26/09/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	19/09/2018	ER6029A	0	33368	79/DS/ER6029A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3601146069	2NR5265992	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:ECICS TP VEH:GBM162Z DATE OF ACC:25/09/2024 NUMBER OF REPAIR DAYS: SURVEY BY:				100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P ARTS				2304.00
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS				1888.00
5	B	BP-LAB2 TO CHECK WIRING SYSTEM				97.92
6	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				144.00
7	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT				432.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				144.00
9	S	BP-SUBLET TO SUPPLY REAR NUMBER PLATE				80.00
10	1	S52159-0U963 COVER, RR BUMPER L/C	1.00	818.00	30.00	572.60
11	2	S52462-0D020 PAD, RR BUMPER, RH	2.00	15.40	30.00	21.56
12	3	S75895-0D270 TAPE, MOULDING, NO.1	2.00	69.90	30.00	97.86
13	4	S52161-0K040 PIECE, RR BUMPER	8.00	5.80	30.00	32.48
14	5	S52575-0D340 RETAINER, RR BUMPER	1.00	236.70	30.00	165.69

For & on behalf of Borneo Motors (Singapore) Pte Ltd	<b>Customer's Signature</b>	<b>Charge Summary</b>	<b>Total</b>
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS	Ms Julis Tng Sok Luan 672A Klang Lane #08-109 Singapore 211672  Mobile: 91854912
	Document No. 0	
	Document Date 26/09/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	NSP151R	AEXRKT E1	19/09/2018	ER6029A	0	33368	79/DS/ER6029A

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3601146069	2NR5265992	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	6	S52576-0D330 RETAINER, RR BUMPER	1.00	236.70	30.00	165.69
16	7	S52023-0D090 REINFORCEMENT SUB-AS	1.00	512.40	30.00	358.68
17	8	S58307-0D480 PANEL SUB-ASSY, BODY	1.00	1134.50	30.00	794.15
18	9	S64401-0D360 PANEL SUB-ASSY, LUGG	1.00	1218.30	30.00	852.81
19	0	S64600-0D040 LOCK ASSY, LUGGAGE C	1.00	553.10	30.00	387.17
20	1	S58387-0D200 PLATE, RR FLOOR FINI	1.00	385.80	30.00	270.06
21	2	S75431-02090 EMBLEM, LUGGAGE COMP	1.00	85.60	30.00	59.92
22	3	S75442-0D400 PLATE, LUGGAGE COMPT	1.00	63.20	30.00	44.24
23	4	S75444-0D690 PLATE, LUGGAGE COMPT	1.00	49.20	30.00	34.44
24	5	SPC507-0D015 73 BACK SENSOR 4W0 QUARTZ BROWN M	1.00	197.80	30.00	138.46

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	9,285.73
	Please acknowledge receipt of vehicle	Parts	3,995.81	GST 9.00%
Labour		5,209.92		
Sublet		80.00		
Lubrication/Fluid		0.00	Less	0.00
Others		0.00	Amount Due	10,121.45

Customer Copy