

ASS. REC. BY:

REF:

AIG/

379 / Kma3 (M)

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Optime

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8109K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PNG 92613

Yr Regn:

C9, 2.2

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Scenic

c.c

1461

Colour

N.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

205376

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1RFA 00063211927

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / SI/Rlm / STD A/Rlm or

Tyre Size:

F: B.S 195/55R20

R: Greenlander

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

8

mm

L/Bal.

2

mm

L/Bal.

8

mm

D.O.A.

17/10/24

D.O.I.

23/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision. ✓

Date / Time

Action / Instruction

28/14 Got B2
L1 Imp & 45,000 Cash

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg.Year: 15.9.2022

NOT Withheld
Renault B4 part
18 days

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Rn</i> \$1,500.00
2	REAR LH BUMPER RETAINER	1		<i>CM</i> \$500.00
3	REAR RH BUMPER RETAINER	1		<i>Sn</i> \$500.00
4	REAR LH BUMPER SIDE SUPPORT BRACKET	1		<i>Rn</i> \$300.00
5	REAR RH BUMPER SIDE SUPPORT BRACKET	1		<i>CM</i> \$300.00
6	REAR BUMPER LOWER	1		<i>Rn</i> \$1,200.00
7	REAR BUMPER LOWER OUTER MOULDING	1		<i>Rn</i> \$1,000.00
8	REAR LH BUMPER REFLECTOR	1		<i>CM</i> \$420.00
9	REAR REVERSE SENSOR	<i>2</i>	<i>A</i> <i>Short</i> \$425.00	\$1,700.00
10	REAR BUMPER CENTER BRACKET	1		<i>CM</i> \$450.00
11	REAR BUMPER TOWING COVER	1		<i>Od</i> \$120.00
12	REAR BUMPER REINFORCEMENT	1		<i>Rn</i> \$900.00
13	REAR LH BUMPER UNDER COVER	1		<i>Dir</i> \$300.00
14	REAR BUMPER CENTER UNDER COVER	1		<i>CM</i> \$450.00
15	REAR LH BUMPER LOWER BRACKET	1		<i>Rn</i> \$300.00
16	REAR RH BUMPER LOWER BRACKET	1		<i>Rn</i> \$280.00
17	REAR BUMPER CENTER INNER LOWER BRACKET	2	\$280.00	<i>CM</i> \$560.00
18	TAILLAMP LH	1		<i>Bo</i> \$960.00
19	TAILLAMP RH	1		<i>Sn</i> \$960.00
20	REAR END PANEL OUTER	1		<i>Rn</i> \$1,800.00
21	REAR LH END PANEL OUTER EXTENSION	1		<i>Rn</i> \$750.00
22	REAR LH END PANEL OUTER EXTENSION	1		<i>Rn</i> \$1,500.00
23	REAR END PANEL INNER	1		<i>mg</i> <i>CM</i> \$680.00
24	REAR END PANEL TRIM BOARD	1		<i>CM</i> \$90.00
25	SMART KEY ANTENNA	1		<i>Rn</i> \$4,000.00
26	REAR BOOT	1		<i>Rn</i> \$300.00
27	REAR BOOT RENAULT LOGO	1		<i>Rn</i> \$200.00
28	REAR BOOT SCENIC EMBLEM	1		<i>Rn</i> \$280.00
29	REAR BOOT RENAULT EMBLEM	1		<i>Rn</i> \$950.00
30	BOOT REFLECTOR LAMP LH	1		<i>mg</i> <i>CM</i> \$950.00
31	BOOT REFLECTOR LAMP RH	1		<i>CM</i> \$1,400.00
32	REAR BOOT OUTER GARNISH	1		<i>Dir</i> <i>Od</i> \$500.00
33	REAR BOOT WEATHERSTRIP	1		<i>Sn</i> \$250.00
34	REAR BOOT LOCK	1		<i>CM</i> \$800.00
35	REAR BOOT OUTER STRIP MOULDING	1		<i>mg</i> <i>CM</i> \$1,400.00
36	REAR SPOILER	1		<i>Shardow</i> \$1,800.00
37	REAR WINDSCREEN	1		<i>Sn</i> \$300.00
37	REAR WIPER ARM	1		

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18-10-2024
 Vehicle No: SNG9261B
 Model: Renault Scenic
 Chassis: VF1RFA00063211927
 Reg.Year: 15.9.2022

Third Party Insurer: AIG
 Third Party Veh No: GU8200T
 Date of Accident: 17/10/2024
 Estimator: Loong
 Surveyor:

38	REAR WIPER BLADE	1		Sm \$150.00	X
39	REAR BOOT OUTER OPENING SWITCH	1		Sm \$200.00	X
40	REAR LICENCE PLATE LAMP	1		Sm \$90.00	X
41	REAR BOOT INNER LOWER TRIM BOARD	1		CM \$1,500.00	X
42	REAR BOOT INNER UPPER TRIM BOARD	1	mg	CM \$360.00	X
43	REAR LH BOOT INNER UPPER TRIM BOARD	1		Sm \$400.00	X
44	REAR RH BOOT INNER UPPER TRIM BOARD	1		Sm \$340.00	X
45	REAR LH BOOT HINGE	1		R \$560.00	X
46	REAR RH BOOT HINGE	1		R \$560.00	X
47	REAR LH BOOT STRUT	1		Sm \$300.00	X
48	REAR RH BOOT STRUT	1		Sm \$300.00	X
50	REAR LH LUGGAGE SIDE TRIM	1		Ref \$1,300.00	X
51	REAR LH LUGGAGE SIDE TRIM CENTER GARNISH	1		CM \$1,000.00	X
52	REAR LH LUGGAGE SIDE TRIM UPPER GARNISH	1		CM \$2,200.00	X
53	REAR RH LUGGAGE SIDE TRIM	1		Sm \$1,300.00	X
54	REAR RH LUGGAGE SIDE TRIM UPPER GARNISH	1		CM \$2,100.00	X
55	ROOF LINING	1		Return \$3,600.00	X
56	REAR ROOF PANEL	1		Buc R \$6,100.00	X
57	REAR ROOF PANEL INNER MEMBER COVER	1		Return \$3,600.00	X
58	REAR LH FENDER PANEL OUTER	1		Buc \$4,850.00	X
59	REAR LH FENDER PANEL AIR VENT	1		Sm \$150.00	X
60	TAILLAMP PANEL LH	1		Buc \$1,050.00	X
61	REAR LH FENDER PANEL QUARTER GLASS	1		nn \$1,000.00	X
62	REAR EXHAUST TAIL PIPE	1		Bz \$1,200.00	X
63	REAR EXHAUST TAIL PIPE HEAT SHIELD - FRONT	1		Sm \$360.00	X
64	REAR EXHAUST TAIL PIPE HEAT SHIELD - REAR	1		Ref \$400.00	X
65	REAR AXLE	1		Bz \$7,800.00	X
66	REAR LH AXLE STUB	1		NN \$1,600.00	X
67	REAR LH ABS SENSOR BRACKET	1		R \$120.00	X
68	REAR LH BRAKE DISC DUST COVER	1		Sm \$100.00	X
69	REAR LH SUSPENSION SHOCK ABSORBER	1		Bz \$360.00	X
70	REAR LH ABS SENSOR	1		Sm \$180.00	X
71	REAR LH WHEEL RIM	1		REPAIR	X
72	REAR LH DOOR PANEL	1		REPAIR	X
73	REAR RH FENDER PANEL	1		REPAIR	X
74	REAR LH CHASSIS	1		REPAIR	X
75	REAR RH CHASSIS	1		REPAIR	X
76	REAR ROOF INNER MEMBER	1		REPAIR	X

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 18-10-2024
 Vehicle No: SNG9261B
 Model: Renault Scenic
 Chassis: VF1RFA00063211927
 Reg.Year: 15.9.2022

Third Party Insurer: AIG
 Third Party Veh No: GU8200T
 Date of Accident: 17/10/2024
 Estimator: Loong
 Surveyor:

SUB TOTAL	\$75,780.00
LESS 10%	-\$7,578.00
PARTS TOTAL	\$68,202.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Na \$55.00
2	REAR BUMPER LOWER CLIPS	1		Na \$50.00
3	REAR BUMPER UNDER COVER CLIPS	1		Na \$50.00
4	REAR BOOT INNER TRIM BOARD CLIPS	1		Na \$50.00
5	REAR WINDSCREEN AND QUARTER GLASS SEALANT	1	Na	401N \$150.00
6	REAR WINDSCREEN AND QUARTER GLASS PRIMER	1	Na	301N \$100.00
7	REAR WINDSCREEN MOULDING	1		Na \$150.00
8	REAR RECORDING CAMERA ON REAR WINDSCREEN	1		Na \$500.00
9	REAR WINDSCREEN SOLAR FILM	1		Na \$400.00
10	REAR BOOT OUTER GARNISH CLIP	1		Na \$50.00
11	REAR END PANEL OUTER & INNER SEALANT	1		Na \$150.00
12	REAR FENDER PANEL SEALANT	1		Na \$100.00
13	REAR LICENCE PLATE NUMBER WITH FRAME	1		Na \$55.00
14	TAILLAMP GUIDE CLIPS	1		Na \$50.00
15	REAR REVERSE SENSOR MOUNTING BRACKET SET	1		Na \$200.00
16	REAR EXHAUST TAIL PIPE MOUNTING AND GASKET SET	1		Na \$50.00
17	REAR SPOILER CLIPS	1		Na \$50.00
18	ROOF LINING CLIPS	1		Na \$50.00
19	REAR ROOF PANEL SEALANT	1		Na \$100.00
20	REAR WINDSCREEN "PRIVATE HIRE" DECAL FROM LTA	1		Na \$80.00
S/N TOTAL				\$2,440.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

2000
\$2,800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL OUTER & INNER, REAR LH & RH FENDER, REAR LH DOOR, REAR BOOT OUTER GARNISH, REAR LH CHASSIS, TAILLAMP PANEL LH, REAR END PANEL OUTER EXTENSION, REAR ROOF INNER MEMBER, REAR BODY DRIP PANEL

1400
\$3,500.00

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN AND QUARTER GLASS TO ENABLE BODYWORK REPAIR

\$180.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18-10-2024
Vehicle No: SNG9261B
Model: Renault Scenic
Chassis: VF1RFA00063211927
Reg.Year: 15.9.2022

Third Party Insurer: AIG
Third Party Veh No: GU8200T
Date of Accident: 17/10/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

601
\$120.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

601
\$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$200.00 1201

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$250.00 2001

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 201

TO REMOVE AND REFIT REAR LUGGAGE COMPARTMENT INNER TRIMMINGS, LININGS, COVER, CUSHION SEAT, GARNISH AND OTHER NEC ITEMS TO ENABLE BODYWORK REPAIR

\$650.00 1201

TO R&R TYRE AND RIM

UN \$100.00 X

TO REMOVE AND REFIT REAR UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR

\$400.00 3001

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

\$150.00 601

TO REMOVE AND REFIT REAR EXHAUST PIPE TO ENABLE BODYWORK REPAIR

\$170.00 601

MOUNT WORKBENCH - TO REALIGNMENT REAR CHASSIS AND REPAIR ACCIDENT AREAS

\$450.00 2501

LABOUR TOTAL \$9,190.00

TOTAL \$79,832.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	900K

Vehicle Details

Vehicle No.:	SNG9261B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Oct 2024
Vehicle Make:	RENAULT
Vehicle Model:	GRAND SCENIC IV 1.5 DCI AT EU6
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	K9KF649D060274
Chassis No.:	VF1RFA00063211927
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$25,525.00
Original Registration Date:	15 Sep 2022
First Registration Date:	15 Sep 2022
Transfer Count:	0
Actual ARF Paid:	\$12,735.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2032
PARF Rebate Amount:	\$9,551.00

Intended COE Rebate Details

COE Expiry Date:	14 Sep 2032
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$68,001.00
COE Rebate Amount:	\$53,787.00
Total Rebate Amount:	\$63,338.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 17 Oct 2024

OK