

LLM AUTO

LLM Auto Leasing Pte Ltd
c/o 1 Kaki Bukit Ave 6, Block C, #01-56
Singapore 417883

TEL : 96155115

EMAIL : llmautoleasing@gmail.com

not Authorised
in
Merous

28/10/24

3 days 2/5 # 2300 /
Telephone After 12pm

VEHICLE No: SNH 9893Y

NETT ITEM

1PC	REAR BUMPER	cut/torn	\$1,088.20	✓
1PC	RAER BUMPER SIDE RETAINER N/S	su	\$108.80	x
1PC	REAR BUMPER REFLECTOR N/S	n1	\$82.10	x
1SET	REAR BUMPER CLIPS	su	\$50.00	✓
1PC	RAER FENDER N/S	R	\$1,425.20	x
1PC	REAR FENDER UNDER SHIELD N/S	n1	\$277.80	x
1PC	REAR SPORT RIM N/S	cut	\$1,299.20	✓
			\$4,331.30	
			LESS 10%	\$3,898.17

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR	\$50.00	30
TO SPRAY RUST PROOFING	n1	\$80.00 x
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	n1	\$80.00 x
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$680.00 250
TO PUTTY & SPRAY PAINTING		\$800.00 400
TOTAL	\$5,638.17	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: