



SC Auto Industries (S) Pte Ltd

51, Senoko Road, Singapore 758133

Tel: 67582222 Fax: 62576931

Email: sales@scauto.com.sg

Website: www.scauto.com.sg

Co.Reg.No.: 199800107D

GST Reg.No.: 199800107D

QUOTATION

Bill To: 2CG001S

CITYLINE GLOBAL PTE LTD
101A UPPER CROSS STREET
#08-14 PEOPLE PARK CENTRE
SINGAPORE 058358

Quotation No. : Q242998-00 Currency : SGD
Date : 22/10/2024 Pay Terms : COD
Vehicle In : 21/10/2024 Advisor : Sai San Phyoo
Time In : 8:57:12 AM Driver Name : CITYLINE DRIVER
Contact No. : ****

MEMBER TYPE:

| Veh No | Reg Date | Make | Model | Chassis No | Mileage | Body Type |
|---------|----------|------|-------|------------|---------|-----------|
| PD9281K | | | | OVH02749 | | |

| S/N | Work Code | Description | Qty | UOM | Unit Price | Dis(%) | Net Price |
|-----|-----------|---|--------------|-----|------------|--------|-----------|
| 1 | SO4 | TO SUPPLY LABOUR AND MATERIAL THE FOLLOWING: MATERIALS: 1. FIBER REAR CAP SC NEUSTAR COACH - \$3140.4 2. SELANAT - \$47 x 16Pcs = \$752 3. COMPANY LOGO STICKER - \$900 | (Fibre type) | | SR | | 4,792.40 |

Authorised Signatory

SC AUTO INDUSTRIES (S) PTE LTD

I/We hereby confirmed the above order

Name & Signature, Company Stamp



SC Auto Industries (S) Pte Ltd

51, Senoko Road, Singapore 758133
Tel: 67582222 Fax: 62576931
Email: sales@scauto.com.sg
Website: www.scauto.com.sg
Co.Reg.No.: 199800107D
GST Reg.No.: 199800107D

QUOTATION

Bill To:

CITYLINE GLOBAL PTE LTD
101A UPPER CROSS STREET
#08-14 PEOPLE PARK CENTRE
SINGAPORE 058358

Quotation No. : Q242998-00 Currency : SGD
Date : 22/10/2024 Pay Terms : COD
Vehicle In : 01/01/0001 Advisor : Sai San Phyo
Time In : 8:57:12 AM Driver Name : CITYLINE DRIVER
Contact No. : ****

MEMBER TYPE:

| | | | | | | | |
|---|-----|--|--|--|--|--|------------------|
| 2 | SCI | Removal of Existing Components: Rear Tail Lamp: - Disconnect the electrical wiring and any mounting hardware securing the rear tail lamp. - Carefully remove the tail lamp from the rear wall fiber cover. Back Camera and Reflector: - Disconnect the camera's electrical connections. - Remove any mounting screws or brackets holding the back camera in place and remove the reflector from the rear cap. - Carefully detach the back camera from the rear wall fiber cover. Removal of Fiber Rear Cap: - Inspect and remove any additional fasteners or clips securing the rear wall fiber cover. - Carefully detach the rear wall fiber cover from the bus, ensuring no damage to surrounding areas or components. - Clean the mounting area on the bus to remove any residual sealant, dirt, or debris. Installation of New Rear Cap Fiber: - Position the new rear fiber cover onto the bus. - Apply sealant and glue to the bus structure components of the rear cap. - Secure the fiber cover using the appropriate fasteners and clips, ensuring a proper fit. - Ensure that all mounting holes and alignment points are correctly aligned with the bus structure. 800X1 | | | | | 3,200.00 2400 |
|---|-----|--|--|--|--|--|------------------|

Authorised Signatory

SC AUTO INDUSTRIES (S) PTE LTD

I/We hereby confirmed the above order

Name & Signature, Company Stamp



SC Auto Industries (S) Pte Ltd

51, Senoko Road, Singapore 758133
Tel: 67582222 Fax: 62576931
Email: sales@scauto.com.sg
Website: www.scauto.com.sg
Co.Reg.No.: 199800107D
GST Reg.No.: 199800107D

QUOTATION

Bill To:

CITYLINE GLOBAL PTE LTD
101A UPPER CROSS STREET
#08-14 PEOPLE PARK CENTRE
SINGAPORE 058358

Quotation No. : Q242998-00
Date : 22/10/2024
Vehicle In : 01/01/0001
Time In : 8:57:12 AM

Currency : SGD
Pay Terms : COD
Advisor : Sai San Phyo
Driver Name : CITYLINE DRIVER
Contact No. : ****

MEMBER TYPE:

| | | | | | | | | |
|---|-----|---|--|--|--|--|------|----------|
| 3 | SC2 | Electrical Work: \$240 Back Camera and reflector: - Reinstall the back camera and reflector by securing it with mounting screws or brackets. - Reconnect the camera's electrical connections. Rear Tail Lamp: - Reposition the rear tail lamp and secure it with the appropriate mounting hardware. - Reconnect the electrical wiring to the tail lamp. - Test all electrical systems for proper functionality before proceeding | | | | | 120 | 250.00 |
| 4 | SC4 | Priming and Painting: - Prepare vehicle for painting (sand, prime, mask) - Apply paint to coach (base coat, clear coat) - Apply additional coats as necessary - Touch up and blend paint to match original finish - Inspect and test paint to ensure quality and accuracy - Apply the company logo sticker NOTE: ADDITIONAL CHARGES MAY APPLY FOR PART, MATERIAL OR LABOUR NOT LISTED ABOVE. | | | | | 1200 | 2,400.00 |

Charges Summary

Parts & Materials : 0.00
Labour : 10,642.40
Others :
Total : 10,642.40

Reward Discount 0.00
Special Discount 0.00
Total Amount 10,642.40
GST 9% 957.82
Amount Payable 11,600.22

Remarks:

Steve (LKK)
28/10/24, 10.00am

m IL
PIP

4 BL m
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: .

Date:

I/We hereby confirmed the above order

Name & Signature, Company Stamp