



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGS SINGAPORE 048581 ATTN: CHRIS LIM			Ref: CS/FCI24100396/Eqp3e2(N) Date: 17/06/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7781H	Veh. Inspected	SND 3545M
	Policy No.	D-24101861MFCT	Coverage (\$)	0.00
	Claim No.	D24009289MFCT	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	22/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	KIA CARNIVAL 2.2 DIESEL 8 SEATER	c.c	2151
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	KNANC81BMN6151996	Colour	BLACK
	Odometer	98161 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R19	GOODYEAR	6 mm
	L/H Front Tyre	235/55 R19	GOODYEAR	6 mm
	R/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
	L/H Rear Tyre	235/55 R19	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/10/2024	Inspection Date	23/10/2024
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	