







CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU  24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587  Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
Z TEXT TP CLAIM COMFORT / DOA SUR OO REPAIR DAYS					<del>4480</del> 6400.00
E PNT88000 TO REPLACE REAR BUMPER, TAIL GATE, REAR END PANEL, REAR FLOOR PANEL, REAR LHS FENDER REPAIR ACCIDENT AFFECTED AREA					<del>2750</del> 3300.00
E PNT98000 PAINT WORK REAR BUMPER, TAIL GATE, REAR END PANEL, REAR LHS FENDER REAR FLOOR PANEL					600.00
E PNT88000 TO MOUNT VEHICLE ON FLOOR BENCH TO ALIGN CHASSIS					<del>120</del> 240.00
E PNT88000 TO REMOVE & REFIT REAR PARKING SENSOR					<del>320</del> 640.00
E PNT88000 TO TRANSFER PARTS & COMPONENTS TO NEW TAIL GATE					380.00
E PNT88000 TO REMOVE & REFIT REAR WINDSCREEN					<del>80</del> 150.00
E PNT88000 TO PERFORM WATER LEAK TEST					120.00
M SUNDRY SUPPLY AND APPLY WINDSCREEN SEALANT					640.00
E PNT88000 TO REMOVE & REFIT ELECTRONIC, PARTS, AND COMPONENT ON REAR BOOT COMPARTMENT TO FACILITATE THE REPAIR					<del>180</del> 320.00
M SUNDRY ANTI-RUST PROOFING					<del>180</del> 320.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREA					<del>320</del> 640.00
E PNT88000 TO REMOVE & REFIT REAR SEAT BENCH					

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
JONATHAN PETER LAU	Cust No/Name /JONATHAN PETER LAU
24 ETTRICK TERRACE	Reg No/Reg Date SND3545M / 23/12/2021
01-01 FRANKEL ESTATE	Date In/Mileage / 0
SINGAPORE 458587	Chassis No KNANC81BMN6151996
Contact No Mobile: 96688763	Engine No D4HEMH705449
	Make/Model KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
A 54900099 TO REMOVE & REFIT FUEL TANK							640? 960.00
A 54900099 TO CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							100 280.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							380.00
M SUNDRY SUPPLY REAR LICENSE PLATE WITH CASING							X 85.00
M SUNDRY C&C EMBLEM							50.00
M SUNDRY SUNDRIES							20 80.00
M COVER-RR BUMPER,UPR				1.00	940.00	00.00	940.00
M COVER-RR BUMPER LWR				1.00	511.00	00.00	511.00
M SKID PLATE-RR BUMPER				1.00	452.00	00.00	452.00
M COVER-RR BUMPER UNDER,LH				1.00	33.00	00.00	33.00
M LAMP ASSY-SIDE T/SIG & REAR,LH				1.00	151.00	00.00	151.00
M LAMP ASSY-SIDE T/SIG & REAR,RH				1.00	151.00	00.00	151.00
M ANTENNA ASSY-SMARTKEY				1.00	45.00	00.00	45.00
M WIRING HARNESS-RR BUMPER				1.00	427.00	00.00	427.00
M BEAM-RR BUMPER				1.00	313.00	00.00	313.00
M BRACKET-RR BEAM LWR MTG,LH				1.00	37.00	00.00	37.00
M BRACKET-RR BEAM LWR MTG,RH				1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,LH				1.00	37.00	00.00	37.00
M BRACKET-RR BUMPER RAIL LWR,RH				1.00	6.00	00.00	6.00
M STAY-RR BUMPER LH				1.00	67.00	00.00	67.00
M STAY-RR BUMPER RH				1.00	67.00	00.00	67.00
M BRACKET ASSY-RR BUMPER SIDE,LH				1.00	23.00	00.00	23.00
M BRACKET ASSY-RR BUMPER SIDE,RH				1.00	23.00	00.00	23.00
M LAMP ASSY-REAR FOG				1.00	133.00	00.00	133.00
M PANEL ASSY-TAIL GATE				1.00	2136.00	00.00	2136.00
M HINGE ASSY-TAIL GATE,LH				2.00	25.00	00.00	50.00
M DRIVE UNIT ASSY-PWR T/GATE,LH				1.00	853.00	00.00	853.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU  24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587  Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	DRIVE UNIT ASSY-PWR T/GATE, RH				1.00	853.00	00.00	853.00
M	TRIM ASSY-TAIL GATE LWR				1.00	383.00	00.00	383.00
M	W/STRIP-TAIL GATE OPNG				1.00	130.00	00.00	130.00
M	W/STRIP ASSY-T/GATE A/PINCH, LH				1.00	223.00	00.00	223.00
M	W/STRIP ASSY-T/GATE A/PINCH, RH				1.00	223.00	00.00	223.00
M	OUTSIDE HDL & LOCK ASSY-T/LID				1.00	177.00	00.00	177.00
M	GARNISH ASSY-TAIL GATE				1.00	624.00	00.00	624.00
M	SCREW-TAPPING				2.00	1.00	00.00	2.00
M	SEALING PAD-B/PNL MLDG NO.2				18.00	1.00	00.00	18.00
M	CLIP-SIDE GARNISH MTG				10.00	3.00	00.00	30.00
M	T/SCREW-COUNTERSINK HEAD				8.00	1.00	00.00	8.00
M	SEALING PAD-B/PNL MLDG NO.4				2.00	1.00	00.00	2.00
M	SEALING PAD-B/PNL MLDG NO.1				2.00	4.00	00.00	8.00
M	PAD-TAIL GATE GARNISH				2.00	2.00	00.00	4.00
M	CAP NUT-RADIATOR, UPR				2.00	4.00	00.00	8.00
M	SEALING PAD-B/PNL MLDG NO.3				2.00	1.00	00.00	2.00
M	EMBLEM-KIA				1.00	54.00	00.00	54.00
M	EMBLEM-CARNIVAL				1.00	89.00	00.00	89.00
M	PANEL ASSY-BACK				1.00	633.00	00.00	633.00
M	TRIM ASSY-RR TRANSVERSE				1.00	99.00	00.00	99.00
M	PAD-WINDSHIELD GLASS				14.00	2.00	00.00	28.00
M	TERMINAL-RR WDO GLASS DEFOGGER				2.00	18.00	00.00	36.00
P	STOPPER-TAIL GATE GLASS				2.00	3.00	00.00	6.00
M	HOUSING-FUEL FILLER DR				1.00	268.00	00.00	268.00
M	LAMP ASSY-CENTER GARNISH				1.00	1910.00	00.00	1910.00
M	GUARD ASSY-REAR WHEEL, LH				1.00	193.00	00.00	193.00
M	ULTRASONIC SENSOR-S.P.A.S				4.00	177.00	00.00	708.00
M	TRIM ASSY-TAIL GATE UPR				1.00	44.00	00.00	44.00
M	TRIM ASSY-TAIL GATE FRAME SIDE				1.00	29.00	00.00	29.00
M	TRIM ASSY-TAIL GATE FRAME SIDE				1.00	29.00	00.00	29.00
M	PAD-ANTINOISE				10.00	1.00	00.00	10.00
M	TRIM ASSY-LUGGAGE SIDE LH				1.00	626.00	00.00	626.00
M	TRIM ASSY-LUGGAGE SIDE RH				1.00	670.00	00.00	670.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 68661666



Movement that inspires

Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
JONATHAN PETER LAU  24 ETTRICK TERRACE 01-01 FRANKEL ESTATE SINGAPORE 458587  Contact No Mobile: 96688763	Cust No/Name	/JONATHAN PETER LAU
	Reg No/Reg Date	SND3545M / 23/12/2021
	Date In/Mileage	/ 0
	Chassis No	KNANC81BMN6151996
	Engine No	D4HEMH705449
	Make/Model	KIA/CARNIVAL 2.2 A D SR G641 8 SEAT
	Colour/Trim	ABP AURORA BLACK / GYT BLACK/GRAY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00087	Cash	22/10/2024/ 15:55	TLL	1210/ Lim Teng Keat	11536
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	PANEL ASSY-REAR FLOOR,RR	1.00	264.00	00.00	264.00
M	PANEL ASSY-REAR FLOOR,FRT	1.00	498.00	00.00	498.00
M	WIRING ASSY-FLOOR	1.00	3974.00	00.00	3974.00
M	CARPET ASSY-REAR FLOOR	1.00	449.00	00.00	449.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SURVEYOR NAME: RASUL - Hy 90010068SURVEYOR SIGNATURE: [Signature]DATE: 23/10/24REMARKS: 12 daysRes by paint

Confirm &amp; accepted by

Nett	35,389.00
9% GST on	35389.00
	3185.01
<b>Total Payable</b>	<b>38,574.01</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# Kia Carnival Diesel 2.2A Sunroof

**\$199,888** Instalment \$1,747/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



## Overview Financial Photo Research

Depreciation	\$25,840 / year
Reg. Date	06-Aug-2021 (6yrs 9mths 12days COE left)
Manufactured	2021
Mileage	51,888 km (16.1k / year)
Transmission	Auto
Engine Cap	2,151 cc
Road Tax	\$2,052 / year
Power	148.0 kW (198 bhp) View specs of the <a href="#">Kia Carnival Diesel (2021-2023)</a>
Curb Weight	2,187 kg
Fuel Type	Diesel (Euro 5 Engine and Above)
COE	\$56,032
OMV	\$40,847
ARF	\$49,186
Dereg Value	\$74,899 as of today

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	533A
<b>Vehicle Details</b>	
Vehicle No.:	SND3545M
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	KIA
Vehicle Model:	CARNIVAL 2.2 DIESEL 8 SEATER SUNROOF
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	D4HEMH705449
Chassis No.:	KNANC81BMN6151996
Maximum Power Output:	148.0 kW (198 bhp)
Open Market Value:	\$39,753.00
Original Registration Date:	23 Dec 2021
First Registration Date:	23 Dec 2021
Transfer Count:	0
Actual ARF Paid:	\$47,655.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2031
PARF Rebate Amount:	\$35,741.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Dec 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,089.00
COE Rebate Amount:	\$41,586.00
<b>Total Rebate Amount:</b>	<b>\$77,327.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 24 Oct 2024

OK