

ASS. REC. BY:

REF:

CTZ/

CS/ CTI 24 100397/Knh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$51K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 2983R

Yr Regn:

06.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIP Sylphy

C.C.

1598

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

86771

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAB17.20031865

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/10/24

D.O.I.

28/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/11 @ 1782.70 Cash (Red. \$330, 16%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format:

Lump Sum / I.B.I: (\$)

TOTAL

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMA 2983R
TP/china

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 21/10/2024
TP Veh Reg No: SLT6757M

Claim No: ES2400891
Estimate No: ES2400891/YISHUN
Date: 28 Oct 2024
Policy No: 5148114939
Veh Reg No: SMA2983R
Make/Model: NISSAN NISSAN
SYLPHY 1.6 CVT
Chassis No: MNTBBAB17Z0031865
Engine No: HR16925368C
Reg. Date: 01/06/2018

NOT Withheld

81782.70

Running After Rain

4 days

Estimate Repair Cost to Vehicle No : SMA2983R

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 REAR BUMPER	380.00	1 PC	380.00	—
2 REAR BUMPER LH LAMP	40.00	1 PC	40.00	—
3 REAR BUMPER CLIPS	2.00	6 PCS	12.00	—
4 LH TAILLAMP	195.00	1 PC	195.00	—
5 REAR BOOT EMBLEM (SYLPHY)	70.00	1 PC	70.00	—
			697.00	
	Add 10%		69.70	766.70
Special Net				
6 REVERSE CAMERA	200.00	1 PC	200.00	X
				200.00
Labour				
7 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, TO KNOCK & REPAIR BOOT, REAR END PANEL, REAR LH FENDER AND REALIGN THE SAME	480.00	1 LA	480.00	400
8 PUTTY & RESPRAY ON REAR BUMPER, BOOT, REAR PANEL, REAR LH FENDER	600.00	1 LA	600.00	550
				1,080.00
Total			S\$ 2,046.70	
Add GST @ 9%				184.20
Total Amount payable				S\$ 2,230.90

2112.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62221033
ATTN: Motor Claim Department

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 21/10/2024
TP Veh Reg No: SLT6757M

Claim No: ES2400891
Estimate No: ES2400891/YISHUN
Date: 29 Oct 2024
Policy No: 5148114939
Veh Reg No: SMA2983R
Make/Model: NISSAN NISSAN
SYLPHY 1.6 CVT
Chassis No: MNTBBAB17Z0031865
Engine No: HR16925368C
Reg. Date: 01/06/2018

Estimate Repair Cost to Vehicle No : SMA2983R

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Supplementary 1				
Cost Plus				
1 REAR BUMPER LH SIDE SPONGE	60.00	1 PC <i>CM</i>	60.00	
			60.00	
	Add 10%		6.00	66.00
			Total	S\$ 66.00
			GST Amount	S\$ 5.94
			Total Amount payable	S\$ 71.94

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE