

SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Rep

Date Generated
User ID

TP
AIG
78

Section A - Accident Details

Registration Number	SHF253K
Case Reference Number	TAX/06/24/2010
Registration Date	14/12/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HWEE MING SIANG (WEI MINGXIANG)
Type of Accident	Head to Rear
Accident Date and Time	3/6/2024 6:25 PM
Accident Reported Date and Time	4/6/2024 4:30 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24121544
Special Instruction to ARC, if any	TP/ REAR PORTION/TOS/AIG - LKK
Prepared Date and Time	11/6/2024 10:52 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$0.00
Total Spray Cost	\$1,478.00	\$0.00
Total Spare Part Cost	\$3,967.28	\$0.00
Total Other Cost	\$500.00	\$0.00
TOTAL COST	\$6,790.28	\$0.00
Lump Sum Total	\$8,800.00	\$0.00
Number of Repair Days	7.0	
Prepared / Adjusted By	ARC Manager Team	2 days Tonghai 97977243
ARC / Surveyor Sign Off Date	11/06/2024 11:11 AM	11/6/24 11:30pm Tonghai
Signature		
Remarks		1/5 Resurvey after repair Tonghai 11/6/24

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

 SMRT Autor
 GO Woodlanc
 FAX Number
 Estimator Te
 Accident Rep

Date Genora

User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, If applicab
TO REPAIR REAR PORTION	\$845.00	200
Total Labour	\$845.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicab
TO RESPRAY BUMPER BEAM	\$220.00	x
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR PANEL	\$220.00	x
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$220.00	x
TO RESPRAY FILLER RR BUMPER LH	\$220.00	x
TO RESPRAY FILLER RR BUMPER RH	\$220.00	x
Total Spray Painting & Panel Beating	\$1,478.00	x

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, If applicab
TO WASH AND VACUUM	\$60.00	x
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	y
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	x
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	30
TO REPLACE SUNDRY PARTS	\$100.00	x
Total Other Costs	\$500.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor A
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace Ry	
		5202347030	REAR BUMPER REINFORCEMENT	1.00	\$360.10	25.00	\$270.08	Replace x	
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace y	
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace x	
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace y	
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace y	
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$12.30	25.00	\$18.45	Replace y	
		5259968030	STOPPER, RR BUMPER, RH & LH	2.00	\$4.80	25.00	\$7.20	Replace x	
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace x	
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$127.40	25.00	\$95.55	Replace x	
		5259147050	SEAL, RR BUMPER, RH	1.00	\$95.50	25.00	\$71.63	Replace y	
		5259247040	SEAL, RR BUMPER, LH	1.00	\$95.50	25.00	\$71.63	Replace y	
		5216116010	CLIPS PILCE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace x	
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace AD	
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace x	
		5256647900	FILLER, RR BUMPER, LH	1.00	\$168.60	25.00	\$126.45	Replace y	
		5216947020	COVER, GUARD RR BUMPER LOWER	1.00	\$16.70	25.00	\$12.52	Replace y	
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace x	



User ID

[illegible]