

ASS. REC. BY:

REF:

F667 C9/SUR240602291/Kqn3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8139K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

201.57 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/7 21:00 869001 Carlin (Red & 2511.70, 27%)

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.R. (\$

TP
6.900

Date: 24/6/2024

Vehicle No: SMU6176Y

Model: VOLVO XC40

Chassis: YV1ZACADL2283554

Reg. Year: 2020

Third Party Insurer: MS FIRST CAPITAL

Third Party Veh No: SHB223T

Date of Accident: 16/6/2024

Estimator: JONATHAN

Surveyor:

NOT Withhold
Money B4 pain
4 dan
11/12/2024

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
	RR BOOT <i>2512</i>			\$ <i>Bz</i> 2,700.00
	RR BOOTLID EMBLEM (VOLVO)			\$ <i>M</i> 146.00
	RR BOOTLID EMBLEM (XC 40)			\$ <i>M</i> 146.00
	RR BOOTLID EMBLEM (T4)			\$ <i>M</i> 137.00
	RR BUMPER - COMPLETE		<i>Bul/nd</i>	\$ 1,995.00
	RR ULTRASONIC SENSOR			\$ <i>m/r</i> 349.00
	RR BUMPER REINFORCEMENT <i>1280</i>			\$ <i>Bz</i> 1,440.00
SUB TOTAL				\$ 6,913.00
Less 10%				-\$ 691.30
PARTS TOTAL				\$ 6,221.70

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
	RR BUMPER CLIPS			\$ <i>M</i> 50.00
	RR W/SCREEN SEALANT			\$ <i>M</i> 100.00
S/N TOTAL				\$ 150.00

LABOUR CHARGES:

To remove, replace, repair, readjust & refix RR affected areas

\$ *550* 800.00

To perform wiring checks on electrical systems

\$ 30.00

To remove, putty, repair, sand and respray affected areas

\$ *560* 600.00

To remove, replace & refix bumper sensors

\$ 30.00

To remove, replace & reinstall Bootlid inner mechansim

\$ 30.00

To remove, refix & replace RR Windscreen

\$ 120.00

To perform Adas Checks, Calibration & Programming

\$ 200.00

LABOUR TOTAL \$ 1,810.00

JONATHAN

TOTAL \$ 8,181.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Branch subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Acknowledged by Repairer

Signature:

Date:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 3/7/2024
 Vehicle No: SMU6176Y
 Model: VOLVO XC40
 Chassis: YV1ZACADL2283554
 Reg.Year: 2020

Third Party Insurer: MS FIRST CAPITAL
 Third Party Veh No: SHB223T
 Date of Accident: 45459

SUPPLEMENTARY

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	RR BOOTLID SWITCH OPENING HANDLE	682		Net \$780.00
2	RR LH BUMPER TOP MOLDING COVER		my cm	Net \$420.00
SUB TOTAL				\$1,200.00
LESS 10%				-\$120.00
PARTS TOTAL				\$1,080.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
S/N TOTAL				\$0.00

SUPPLEMENTARY

LABOUR CHARGES:

TO RESPRAY RR LH BUMPER TOP MOLDING COVER

Net \$150.00

1201
 1201

LABOUR TOTAL \$150.00

VIC / TING AN TOTAL \$1,230.00

SWP: PARTS: 1080
 Labour: 150
 TOTAL: 1230

Head office

8 Kung Chong Road Singapore 109143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554560
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569647
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	481Z
Vehicle Details	
Vehicle No.:	SMU6176Y
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2024
Vehicle Make:	VOLVO
Vehicle Model:	XC40 T4 MOMENTUM
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	B4204T473496089
Chassis No.:	YV1XZACADL2283554
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$28,071.00
Original Registration Date:	21 Aug 2020
First Registration Date:	21 Aug 2020
Transfer Count:	0
Actual ARF Paid:	\$31,300.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2030
PARF Rebate Amount:	\$23,475.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,802.00
COE Rebate Amount:	\$23,875.00
Total Rebate Amount:	\$47,350.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 24 Jun 2024

OK