

Kok Wang Car Grooming

GST REG. NO: 09-935300-L

CHINA TAIPIING INSURANCE COMPANY LIMITED
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIMS DEPT

ESTIMATE REPAIR BILL

YOUR REF : SNP5814K
TYPE OF CLAIM : THIRD PARTY CLAIMS
CLAIMANT : HUA YANG ENTERPRISE PTE LTD
VEHICLE NO. : SNN1179U 1197U
MAKE/ MODEL : TOYOTA ALPHARD
ACCIDENT DATE : 21/10/24

MATERIAL COST

1	1PC	REAR BOOTLID	✓	\$	2,577.13	2014.80
2	1PC	REAR BOOTLID CENTRE LOCK	X sue	\$	1,000.25	X
3	1PC	REAR BOOTLID CENTRE LOCK COVER	X sue	\$	249.75	X
4	1PC	REAR BUMPER	de	\$	2,724.25	1254.30
5	2 PCS	REAR BUMPER TOW COVER	de	\$	99.00	35.60
6	4 PCS	REAR BUMPER PARKING SENSOR	2 (1pc) short	\$	1,964.00	180
7	1PC	REAR END PANEL	Repair	\$	X 985.25	Repair
8	3 PCS	WINDSCREEN SILICON		\$	60.00	40
9	1PC	WINDSCREEN MOULDING		\$	195.00	179

LESS : DISCOUNT 25%

3703.70
259
2777.77

\$ 2,463.66
\$ 7,390.97

LABOUR CHARGE :

1	TO SPRAY PAINTING ON AFFECTED BODY PART	\$	1,000.00	500 + 250 = 750
2	TO PANEL BEATING, LABOUR TO REPLACE BODY PART, WEILDING, FITTING AND ALIGNMENT	\$	800.00	500 + 250 = 750
3	TO REMOVE AN REFIX WINDSCREEN	\$	250.00	1730 150
4	TO COMPUTER SETTING AFTER INSTALL PART	\$	120.00	80

\$ 9,560.97

ADD: GST 9% \$ 860.49

TOTAL:

\$ 10,421.46

TOH AH SWEE SPRAY PAINTING CO.
WEI SI (TEL: 63660286)

2777.77
1730.00
4507.77

Rasul
4p 700 10568
5 days
P/P
21/10/24

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

28/08/24
Resurvey after repair

Acknowledged by Repairer
Signature:
Date:

painting \$400

signal switch \$95