



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tan Ban Leng (chen Wanlong)	Cust No/Name /Tan Ban Leng (Chen Wanlong)
42 Tai Keng Gardens	Reg No/Reg Date SMA1660D / 30/05/2018
Singapore 535323	Date In/Mileage / 0
Contact No Mobile: 98766288	Chassis No JMAXTGK1WJZ001687
	Engine No 4B40DL5651
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	23/10/2024/ 15:09		1015/ Vikneswaran Naidu A	51042
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER, SKID PLATE, TAILGATE, REPAIR END PANEL AND RENEW DAMAGED PARTS	1	280.00		280.00
E PNT98000	SPRAY RR BUMPER, TAILGATE, END PANEL	1	1650.00		1650.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	1	280.00		280.00
A 10028901	CHECK WIRING AND ELECTRICAL	1	150.00		150.00
A 10028901	CALIBRATION ON THE REAR AUTO TAILGATE SENSOR	1	280.00		280.00
E PNT88000	REMOVE AND REFIT/TRANSFER REAR TAILGATE MECHANISM TRIM	1	280.00		280.00
E PNT88000	REMOVE AND REFIT SENSOR	1	100.00		100.00
M SUNDRY	SUPPLY NUMBER PLATE	1	100.00		100.00
M SUNDRY	RUST PROOFING	1	200.00		200.00
M SUNDRY	APPLY SEALANT ON AFFECTED AREA	1	150.00		150.00
M SUNDRY	SUPPLY CNC BADGE	1	50.00		50.00
M SUNDRY	SUNDRIES	1	80.00		80.00
E PNT88000	RENEW RR GLASS	1	380.00		380.00
M SUNDRY	SEALING WINDSCREEN	1	100.00		100.00
M SUNDRY	WATER LEAK TEST	1	50.00		50.00
M SUNDRY	SUPPLY SOLAR FILM TINT	1	280.00		280.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tan Ban Leng (chen Wanlong)	Cust No/Name /Tan Ban Leng (Chen Wanlong)
42 Tai Keng Gardens	Reg No/Reg Date SMA1660D / 30/05/2018
Singapore 535323	Date In/Mileage / 0
Contact No Mobile: 98766288	Chassis No JMAXTGK1WJZ001687
	Engine No 4B40DL5651
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00147	Cash	23/10/2024/ 15:09		1015/ Vikneswaran Naidu A	51042
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M FACE,RR BUMPER de	1.00	548.00	00.00	✓ 548.00	
M EXTENSION,RR BUMPER de	1.00	150.00	00.00	✓ 150.00	
M CORE,RR BUMPER de	1.00	41.00	00.00	✓ 41.00	
M CORE,RR BUMPER de	1.00	35.00	00.00	✓ 35.00	
M REINFORCEMENT,RR BUMPER de	1.00	525.00	00.00	✓ 525.00	
M BRKT,R/BMPR FACE SIDE,LH 2 fsv	1.00	26.00	00.00	26.00	
M BRKT,R/BMPR FACE SIDE,RH 2 fsv	1.00	26.00	00.00	26.00	
M COVER,RR BUMPER,LH 2 fsv	1.00	170.00	00.00	170.00	
M COVER,RR BUMPER,LH 2 fsv	1.00	170.00	00.00	170.00	
M PANEL ASSY,TAILGATE 2 fsv	1.00	1125.00	00.00	✓ 1125.00	
M GARNISH,TAILGATE X m	1.00	518.00	00.00	518.00	
M DAM,TAILGATE,LWR m	1.00	14.00	00.00	14.00	
M GLASS,TAILGATE WINDOW m	1.00	670.00	00.00	✓ 670.00	
M SPACER,TAILGATE m	2.00	9.00	00.00	✓ 18.00	
M SPACER,TAILGATE m	2.00	9.00	00.00	✓ 18.00	
M CLIP,TAILGATE m	3.00	4.00	00.00	12.00	
M PIN,TAILGATE WINDOW m	1.00	6.00	00.00	6.00	
M SPACER,QTR WINDOW m	4.00	8.00	00.00	✓ 32.00	
M FASTENER,WINDSHIELD m	8.00	8.00	00.00	✓ 64.00	
M STOPPER,WINDSHIELD GLASS m	2.00	4.00	00.00	✓ 8.00	
M MARK,THREE-DIA m	1.00	61.00	00.00	✓ 61.00	
M MARK,ECLIPSE CROSS m	1.00	92.00	00.00	✓ 92.00	
M MARK,MITSUBISHI m	1.00	81.00	00.00	81.00	

SURVEYOR NAME: Rasur - 409001068

SURVEYOR SIGNATURE: [Signature]

DATE: 28/10/24

REMARKS: 2 days + 4 = 11 days

Res 5K paint.

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Nett	11,820.00
9% GST on	11820.00
Total Payable	12,883.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Tan Ban Leng (chen Wanlong)	Cust No/Name /Tan Ban Leng (Chen Wanlong)
42 Tai Keng Gardens	Reg No/Reg Date SMA1660D / 30/05/2018
Singapore 535323	Date In/Mileage 28/10/2024/ 0
Contact No Mobile: 98766288	Chassis/Package JMAXTGK1WJZ001687 /#
15/11/2024	Engine No 4B40DL5651
	Make/Model MIT/ECLIPSE CROSS 1.5 T/C 2WD (T12)
	Colour/Trim P26 ORIENT RED / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00147	Cash	12/12/2024/ 18:59		1015/ Vikneswaran Naidu A	51042			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1920.00
ADD REPAIR RENEW RR END PANEL								
E PNT98000								550.00
ADD PAINTWORK REAR END PANEL								
A 15900099								320.00
ADD REPAIR REPLACE REAR EXHASUT MUFFLER								
X	DAM, TAILGATE, LWR	rec			1.00	14.00	00.00	14.00
X	PIN, TAILGATE WINDOW	rec			1.00	6.00	00.00	6.00
X	CLIP, TAILGATE	rec			2.00	4.00	00.00	8.00
X	PANEL, RR END	bt			1.00	503.00	00.00	503.00
X	MUFFLER, EXHAUST MAIN	bt			1.00	545.00	00.00	545.00
X	ANT, KEYLESS OPERATION, RR	com			1.00	102.00	00.00	102.00
X	BUZZER, KEYLESS OPERATION, RR	com			1.00	96.00	00.00	96.00
X	COVER, RR BUMPER, LH	com			1.00	170.00	00.00	170.00
X	COVER, RR BUMPER, RH	com			1.00	170.00	00.00	170.00
X	CLIP, BUMPER	rec			8.00	2.00	00.00	16.00
X	CLIPS	rec			10.00	2.00	00.00	20.00
Guarantee Your Warranty, Maintain with Cycle & Carriage!								
Parts	1,650.00					Nett		4,440.00
Labour	2,790.00				9% GST on	4440.00		399.60
Standard Menu	0.00							
Specialist Job	0.00							
Diagnostics Job	0.00							
Sundry/Others	0.00							
Total(w/o GST)	4,440.00					Total Payable		4,839.60