

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0812/2024/KS
DATE : 24-Oct-24
WIP : 35880

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR SIA BEE LENG (XIE MEILING)
ADDRESS : BLK 259 ANG MO KIO AVENUE 2
#20-08
SINGAPORE 560259
TELEPHONE : HP +65 88223533
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 17000075557-06
VEHICLE NO : **SLT 9600 L**
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 14/11/2017
ENGINE NO : CHZ 552573
CHASSIS NO : WAUZZZGA8JA022854
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Oct-24
PLACE OF ACCIDENT : PORTCHESTER AVE & KENSINGTON PARK RD. SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLT 9600 L.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 5,452.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 9600 L.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,253.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 387.00	
3	FRONT BUMPER GRILLE - CENTER	1	\$ 247.00	
4	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 212.00	
5	FRONT BUMPER AIR GUIDE GRILLE END CAP - RH	1	\$ 74.00	
6	FRONT BUMPER SPOILER	1	\$ 374.00	
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 195.00	
8	FRONT WHEEL SPOILER - LH / RH	2	\$ 86.00	
9	FRONT BUMPER ADAPTOR - RH	1	\$ 54.00	
10	FRONT BUMPER GUIDE SECTION - RH	1	\$ 45.00	
11	LED HEADLIGHT - RH	1	\$ 5,892.00	
12	LED HEADLIGHT POWER MODULE - RH	1	\$ 1,904.00	
13	LED HEADLIGHT SPACER - RH	1	\$ 57.00	
14	LIFT CYLINDER - RH	1	\$ 170.00	
15	LIFT CYLINDER HOSE	1	\$ 233.00	
16	LED HEADLIHGT MOUNTING - RH	1	\$ 147.00	
17	FRONT FENDER - RH	1	\$ 1,365.00	
18	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 47.00	
19	FRONT FENDER BRACKET - RH	1	\$ 20.00	
20	FRONT FENDER BRACKET - RH	1	\$ 62.00	
SUB TOTAL SPARE PARTS		:	\$ 12,824.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 9600 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER BRACKET - RH	1	\$ 20.00	
22	FRONT FENDER RIVET - RH	6	\$ 26.00	
23	FRONT FENDER BRACE - RH	1	\$ 67.00	
24	FRONT WHEEL HOUSING LINER - RH	1	\$ 47.00	
25	LED HEADLIGHT BRACKET - RH	1	\$ 57.00	
26	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 804.00	
TOTAL SPARE PARTS		:	\$ 13,845.00	
TOTAL LABOUR CHARGES		:	\$ 5,452.00	
GRAND TOTAL		:	\$ 19,297.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT