



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS GO - LEASE PTE LTD 1 TAMPINES NORTH DRIVE 1, #02-33, T SPACE SINGAPORE 528559		Ref: CS/TP24100433/Enh3e2 Date: 30/10/2024 Code: TP2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	-	Veh. Inspected	SGP 9061Y
Policy No.	-	Coverage	0
Claim No.	-	Excess	\$0.00
Assign From	-	Assign Date	25/10/2024
2. Vehicle Details			
Make & Model	TOYOTA PRIUS C	C.C	1497
Engine No.	-	Year of Reg.	29/11/2016
Chassis No.	JTDKD3B3401588355	Colour	BLACK
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	195/60 R15	MICHELIN	5
L/H Front Tyre	195/60 R15	MICHELIN	5
R/H Rear Tyre	195/60 R15	MICHELIN	5
L/H Rear Tyre	195/60 R15	MICHELIN	5
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, N/S BODY AND INTERIOR. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/09/2024	Inspection Date	25/10/2024
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			