

<b>EURO SUCCESS SERV PTE. LTD</b>			
<b>1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883</b>			
<a href="tel:67426231">TEL: 67426231</a>		<b>FAX: 67411019</b>	<b>H/P: 98289277 (Ah Huat)</b>
Vehicle No:	SGP9061Y		Model: TOYOTA PRUIS
<b><u>QTY</u></b>	<b><u>LIST ITEMS</u></b>		<b><u>PRICE</u></b>
1	FRONT BUMPER		\$600.00
2	FRONT FENDER L-R @500		\$1,000.00
2	FRONT HEADLAMP L-R @800		\$1,600.00
1	FRONT BUMPER REINFORCEMENT		\$450.00
1	BONNET		\$750.00
2	BONNET HINGE @60		\$120.00
1	SUPPORT PANEL		\$550.00
1	FRONT WINDSCREEN		\$600.00
1	FRONT WINDSCREEN MOULDING		\$150.00
1	RADIATOR		\$650.00
2	RADIATOR FAN ASSY @400		\$800.00
1	AIRCON CONDENSER		\$450.00
1	AIRCON COMPRESSOR		\$650.00
2	AIRCON PIPE @300		\$600.00
1	ENGINE MANIFOLD		\$750.00
1	ALTERNATOR		\$550.00
1	ABS PUMP		\$1,800.00
1	ENGINE CHASSIS FRAME		\$700.00
1	WHEEL HUB PANEL L/H		\$500.00
1	ENGINE CROSSMEMBER		\$1,100.00
1SET	ENGINE MOUNTING		\$600.00
1	HYBRID BATTERY (RECON)		\$4,000.00
1	DRIVER AIRBAG		\$1,800.00
1	FRONT PASSENGER AIRBAG		\$1,900.00
2	FRONT SIDE AIRBAG L-R @1350		\$2,700.00
2	REAR SIDE AIRBAG L-R @1100		\$2,200.00
1	ROOFLINING		\$45.00
1	AIRBAG ECU		\$1,500.00
1	FRONT SEAT BELT @850		\$1,700.00
1	FRONT DOOR L/H		\$650.00
1	FRONT DOOR GLASS L/H		\$450.00
1	FRONT SIDE MIRROR L/H		\$500.00
2	FRONT AND REAR DOOR PILLAR L/H		\$1,700.00
		<b>TOTAL</b>	<b>\$34,115.00</b>
	<b><u>LABOUR CHARGES</u></b>		
	TOWING CHARGES		\$150.00
	TO REMOVE & REFIX REAR UNDERCARRIAGE		\$1,000.00
	TO RESPRAY UNDERCOATING		\$400.00
	PANEL BEATING, STRAIGHTEN CHASSIS REMOVE AND REPLACING ABOVE PARTS		\$3,000.00
	TO REMOVE & REFIX WINDSCREEN		\$200.00
	TO CHECK, REMOVE, FIX ELECTRICAL WIRING		\$300.00
	REMOVE & REFIX AIRBAGS		\$1,000.00
	REMOVE & REFIX ROOFLINING		\$200.00
	TO REPSRAY PAINT INCLUDING POLISH & WAXING ON DAMAGED PARTS		\$1,700.00
		<b>TOTAL</b>	<b>\$7,950.00</b>
		<b>TOTAL</b>	<b>\$42,065.00</b>
		<b>LESS</b>	<b>\$14,000.00</b>
	<b>ESTIMATED PARTS AND LABOUR GRAND TOTAL \$</b>		<b>\$28,065.00</b>