

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

Not Authorized
an
more
25/10/24
d/s & S-500/
chept. Arthur
5 days

VEHICLE No: SLP 3469K

1PC	REAR WINDSCREEN	SVC		\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	N/S		\$148.30	X
1PC	TAILGATE	DD/Bnf		\$1,602.20	✓
1PC	TAILGATE REAR LOGO	neu		\$68.50	✓
2PCS	TAILGATE REFLECTORS @\$413.00	11		\$826.00	X
1PC	TAILGATE WEATHERSTRIP	neu		\$357.00	✓
1PC	TAILGATE INNER LOCK	DD/Bnf		\$489.80	✓
1PC	TAILGATE LOCK STIRKER	neu		\$60.00	X
1PC	REAR BUMPER	DD/Bnf	50/70	\$622.30	✓
1PC	REAR BUMPER CENTRE BLACK GARNISH	Dis	288-50	\$386.70	✓
1PC	REAR BUMPER REFLECTOR	11		\$75.20	X
2PCS	REAR BUMPER SIDE BLACK GARNISHS @\$195.50	gross/70cm		\$391.00	✓
1PC	REAR BUMPER LAMP CENTRE	11		\$335.20	X
1PC	REAR BUMPER SIDE RETAINER N/S	11		\$130.00	X
1PC	REAR END PANEL OUTER	DD/Bnf		\$699.10	✓
1PC	REAR END PANEL INNER	DD/Bnf		\$559.10	✓
1PC	REAR ANTENNA SENSOR	neu	199-60	\$350.00	✓
1PC	REAR END PANEL TOP GARNISH	neu		\$268.90	✓
2PCS	TAILLAMPS @\$650.50	11		\$1,301.00	X
2PCS	TAILLAMP HOUSING PANELS @\$650.30	R		\$1,300.60	X
1PC	REAR FENDER INNER TRIM BOARD O/S	Su		\$870.20	X
1PC	REAR FLOOR PANEL	R		\$1,415.10	X
1PC	REAR FLOOR PANEL TOP BOARD	Su		\$622.30	X
1PC	REAR FLOOR PANEL TOOLS TRAY	wepd/cro		\$422.80	✓
				\$14,789.40	
				LESS 25%	\$11,092.05

S.NETT

1SET	REAR BUMPER CLIPS	neu		\$50.00	30 S/W
1SET	REAR BUMPER REVERSE SENSOR	malfuction		\$200.00	✓
1SET	REAR BUMPER REFLECTOR	Su		\$80.00	60 S/W
1PC	REAR WINDSCREEN SEALANT	neu		\$50.00	40 S/W
1PC	REAR WINDSCREEN INNER SEAL	neu		\$50.00	20 S/W
1PC	REAR END PANEL SEALANT	neu		\$50.00	50 S/W
1SET	TAILGATE INNER TRIM CLIPS	11		\$50.00	X
1SET	TAILGATE LIZARD STICKER DECAL	neu kiv		\$100.00	X
1SET	TAILGATE STICKER DECAL	neu kiv		\$100.00	X
1SET	TAILGATE OUTER PROTECTOR STRIP	neu kiv		\$80.00	X
1PC	TAILGATE 'MUGEN' EMBLEM	neu		\$60.00	50 S/W

1SET REAR FLOOR PANEL INSULATOR 11
1PC REAR LICENCE PLATE one

\$450.00 X
\$40.00 ✓ 5/22

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	30
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	11 \$100.00	X
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY PROOFING	\$180.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	750
TO PUTTY & SPRAY PAINTING	\$1,500.00	900
TOTAL	\$16,032.05	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5848.4
252
4286.30
490
2000
6876.30
211
5101