

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/MSG 24100454/ULV302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLP 3469K

at Workshop m/s R

of _____

Insured: SMJ 3874T

Policy No. 1002652672

Claims No. 377802


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$42K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 18997

Veh No: SLP 3469K Yr Regn: 31/05/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Sienna c.c 1496

Colour: Green A/C: Insured / Std / NI / NA

Sp. Reading: 104398 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NSP 170 7064825

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 23/10/24 D.O.I. 25/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 24/11/24

22/11/24 2/5 \$500 in hand Alen. (red 10,532.05, 65%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ _____)

Survey Fee:

Transportation:

____ S + RS, ____ SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	563A
Vehicle Details	
Vehicle No.:	SLP3469K
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5X CVT
Primary Colour:	Green
Manufacturing Year:	2016
Engine No.:	2NR8699690
Chassis No.:	NSP1707064825
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,522.00
Original Registration Date:	31 May 2017
First Registration Date:	31 May 2017
Transfer Count:	1
Actual ARF Paid:	\$9,522.00 4761
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 May 2027
PARF Rebate Amount:	\$5,713.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$13,284.00
Total Rebate Amount:	\$18,997.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 24 Oct 2024

OK

- Toyota Sienta 1.5A Standard

\$44,888

Instl. \$1,112 /mth

\$14,000 /yr

25-May-2017 (2yrs 6mths COE left)

120,000 km

1,496 cc

1 owner decent mileage, full agent serviced! With servicing package balance! Cheap MPV ideal for family usage! We welcome all pre workshop checks and evaluations! 6 months warranty provided for peace of mind purchase! Full loan/high loan available! Call now!

Posted 23-Oct-2024

Compare
- Toyota Sienta 1.5A G

\$50,800

Instl. \$1,259 /mth

\$16,840 /yr

16-Jun-2017 (2yrs 7mths COE left)

68,000 km

1,496 cc

Don't miss this chance to drive home a rare 1 owner + low mileage 7 seater! The Toyota Sienta is the perfect compact MPV for small/starting families. Complimentary Unlimited Mileage Warranty on Engine & Gearbox until the end of COE + Servicing Package. Flexible Loan Packages are available with the most attractive interest rates in town!

Car Times Automobile Pte Ltd|Posted 21-Oct-2024

Compare
- Toyota Sienta 1.5A Elegance

\$56,500

Instl. \$1,212 /mth

\$15,670 /yr

26-Oct-2017 (3yrs COE left)

107,824 km

1,496 cc

Drop by Carro to view the largest fleet in Singapore with 100% transparency on our vehicle condition, financing options, service add-ons and many more.

Carro|Posted 21-Oct-2024

Compare

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorized
du
mens
25/10/24
d/s & S-500/
chept. Atkuty-
S-days

VEHICLE No: SLP 3469K

1PC	REAR WINDSCREEN	SUC		\$1,488.10	X
1PC	REAR WINDSCREEN MOULDING	N/S		\$148.30	X
1PC	TAILGATE	DD / Buf		\$1,602.20	✓
1PC	TAILGATE REAR LOGO	neu		\$68.50	✓
2PCS	TAILGATE REFLECTORS @ \$413.00	11		\$826.00	X
1PC	TAILGATE WEATHERSTRIP	7w1		\$357.00	✓
1PC	TAILGATE INNER LOCK	Daye / Buf		\$489.80	✓
1PC	TAILGATE LOCK STIRKER	11		\$60.00	X
1PC	REAR BUMPER	De / 70, 11	50 / 70	\$622.30	✓
1PC	REAR BUMPER CENTRE BLACK GARNISH	D. 5	288-50	\$386.70	✓
1PC	REAR BUMPER REFLECTOR	11		\$75.20	X
2PCS	REAR BUMPER SIDE BLACK GARNISHS @ \$195.50	8004 / 70, 11		\$391.00	✓
1PC	REAR BUMPER LAMP CENTRE	11		\$335.20	X
1PC	REAR BUMPER SIDE RETAINER N/S	11		\$130.00	X
1PC	REAR END PANEL OUTER	DD / Buf		\$699.10	✓
1PC	REAR END PANEL INNER	DD / Buf		\$559.10	✓
1PC	REAR ANTENNA SENSOR	neu	199.60	\$350.00	✓
1PC	REAR END PANEL TOP GARNISH	7w1		\$268.90	✓
2PCS	TAILLAMPS @ \$650.50	11		\$1,301.00	X
2PCS	TAILLAMP HOUSING PANELS @ \$650.30	R		\$1,300.60	X
1PC	REAR FENDER INNER TRIM BOARD O/S	SU		\$870.20	X
1PC	REAR FLOOR PANEL	R		\$1,415.10	X
1PC	REAR FLOOR PANEL TOP BOARD	SU		\$622.30	X
1PC	REAR FLOOR PANEL TOOLS TRAY	weged / 11		\$422.80	✓
				\$14,789.40	
				LESS 25%	\$11,092.05

S.NETT

1SET	REAR BUMPER CLIPS	111		\$50.00	30 S/W
1SET	REAR BUMPER REVERSE SENSOR	melfuction		\$200.00	✓
1SET	REAR BUMPER REFLECTOR	SCA		\$80.00	60 S/W
1PC	REAR WINDSCREEN SEALANT	neu		\$50.00	40 S/W
1PC	REAR WINDSCREEN INNER SEAL	neu		\$50.00	20 S/W
1PC	REAR END PANEL SEALANT	neu		\$50.00	50 S/W
1SET	TAILGATE INNER TRIM CLIPS	11		\$50.00	X
1SET	TAILGATE LIZARD STICKER DECAL	neu kiu		\$100.00	X
1SET	TAILGATE STICKER DECAL	neu kiu		\$100.00	X
1SET	TAILGATE OUTER PROTECTOR STRIP	7w1 kiu		\$80.00	X
1PC	TAILGATE 'MUGEN' EMBLEM	neu		\$60.00	50 S/W

1SET REAR FLOOR PANEL INSULATOR 11
1PC REAR LICENCE PLATE Cne

\$450.00 X
\$40.00 ✓ 5/12

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	30
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	11 \$100.00	X
TO DISMANTLE & REFIX REAR EXHAUST	11 \$100.00	X
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY PROOFING	\$180.00	60
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	750
TO PUTTY & SPRAY PAINTING	\$1,500.00	900
TOTAL	\$16,032.05	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, etc. in workshop
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5848.4

252

4286.30

490

2000

6876.30

213

5801