# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: AIG ASIA PACIFIC INSURANCE PTE LTD From: LKK Auto Consultants Pte Ltd

78 SHENTON WAY #09-16

AIG BUILDING

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: SIM, PRISCILLA-LK Date: 30/08/2024

# **PRELIMINARY ADVICE**

 Vehicle No
 SMH 5262G
 Accident Date
 23/06/2024

 Make
 MAZDA 6
 CLAIM No.
 3736111173SG

Assignment Date 25/06/2024 Excess Inspection Date 26/6/2024 Est. Duration of Repair 7

Inspected At: Sin Yu Sin Workshop

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

 Workshop Estimate Amount:
 \$ 25,452.48

 Revised Estimate Amount:
 \$12,807.44

 "Check" Items Amount
 \$0.00

 Total
 \$12,807.44

### **Total Loss Consideration**

Book Value \$0.00 Market Value \$0.00

COE / PARF Rebate

Salvage Value \$0.00

Margin for Repair

### Remarks

[	]	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

[ ] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

[ ] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.