

ASS. REC. BY:

REF:

CD/012/24100470/kmaz

ASSIGNMENT

From:

Date:

Estimated Cost:

QD/TP/WS/TP RES/QD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 Not B2

4/11 11:20 83300d Car

Veh No:

SUR 6353E

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Merida 3

C.G

1496

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

186292

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN 6BN 22A 8140174/89

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

24/10/24

D.O.I.

25/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07193

Vehicle Insured : SLJ489D

Accident Date : 24-Oct-2024

Date : 24-Oct-2024

Our Ref : 024211 (CHINA) / CHAN

PAGE : 1

CHAN JINGZHONG
43 BRIGHT HILL DRIVE
#19-14
Singapore 573894

*Not withstanding
1/10/24 &
Acting After Repair
6 days*

ESTIMATED COST OF REPAIR FOR MAZDA 3 SLR6353E

1 pc	Rear bumper fascia			<i>ALUM</i>	1,128.00	✓
1 pc	Rear bumper reinforcement			<i>AL</i>	563.00	✓
2 pcs	Rear bumper side retainer	@ S\$ 38.00		<i>CM</i>	76.00	✓
2 pcs	Rear bumper side bracket	@ S\$ 49.00		<i>CM</i>	98.00	✓
2 pcs	Rear bumper towing cover	@ S\$ 26.90		<i>MT</i>	53.80	✓
2 pcs	Rr bumper side clip c/w screw	@ S\$ 5.50		<i>MT</i>	11.00	✓
1 pc	Rear bumper centre top clip			<i>CM</i>	5.90	✓
1 pc	Rear end panel			<i>AL</i>	530.00	✓
1 pc	End panel top garnish			<i>SVC</i>	89.00	X
1 pc	Rear floor panel sponge			<i>CM</i>	158.00	✓
					2,712.70	
Less 20% :					542.54	

1 pc Rear bumper reverse sensor(set)
1 pc Rear bumper clip (set)

*2,170.16 2000
300.00 sn
30.00 sn*

To remove rear seat, trim board and carpet

120.00 600

To apply undersealing

60.00 ✓

To putty and spray replaced parts

1000.00 900

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

900.00 900

Total : S\$ 3,980.16

Singapore Dollars Three Thousand Nine Hundred
and Eighty and Cents Sixteen Only

LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during repair
• Parts prices are subject to confirmation
• Third party survey is on a "Without prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be inspected and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	060D

Vehicle Details

Vehicle No.:	SLR6353E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	24 Oct 2024
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	P520464168
Chassis No.:	JM6BN22A8H0174189
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,700.00
Original Registration Date:	22 Aug 2017
First Registration Date:	22 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$10,700.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Aug 2027
PARF Rebate Amount:	\$6,420.00

Intended COE Rebate Details

COE Expiry Date:	21 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$13,216.00
Total Rebate Amount:	\$19,636.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 24 Oct 2024

OK